

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30702
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Lowe
8. Well No.	1
9. Pool name or Wildcat	King Wolfcamp
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3870 KB

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Bahlburg Exploration, Inc.	
3. Address of Operator P.O. Box 866937, Plano, TX 75086-6937	
4. Well Location Unit Letter M : 900 Feet From The South Line and 50 Feet From The West Line Section 25 Township 13 S Range 37 E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3870 KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to acidize existing Wolfcamp perforations 9856-64' & 9964-90' with 3000 gal. 15% HCL NeFe.

Drill out CIBP set @ 10,084' and clean out hole to top of cement @ 10,124'.

Put well on production using beam pump from perforations 10,119-24', 9964-90' & 9856-64'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE William C. Bahlburg TITLE President DATE 3/15/95

TYPE OR PRINT NAME William C. Bahlburg TELEPHONE NO. 214/867-2575

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAR 21 1995

CONDITIONS OF APPROVAL, IF ANY: _____

MP

140
RECEIVED

100-100000

100-100000