District Office DISTRICT I P.O. Box 1980, Hobbs, NM 88240			esources Department		Revised 1-1-89	
P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION			WELL API NO.	2100	
	P O Box 208		88	30-025-3	2188	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088				FEE XX	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				6. State Oil & Gas Lease	No.	
SUNDRY NOTICES AND REPORTS ON WELLS						
(DO NOT USE THIS FORM FOR PF DIFFERENT RESI (FORM	ROPOSALS IOL	EPORTS ON WE DRILL OR TO DEEPE APPLICATION FOR P DH PROPOSALS.)		7. Lease Name or Unit A	greement Name	
1. Type of Well: GAS		OTHER		Childress AK	<u></u>	
OL WELL WELL		UTHER		8. Well No.		
2 Name of Operator	OD LET ON		· ·	1		
YATES PETROLEUM CORP	ORATION			9. Pool name or Wildcat	Lazy J	
3. Address of Operator	Arto	sia, NM 8821	0	Saunders Permo	Upper Penn	
105 South Fourth Str	eet - Artes	51a, MI 0011				
4. Well Location Unit Letter <u>M</u> : <u>9</u>	90 Feet From	n The <u>South</u>	Line and330) Feet From The	West Line	
		1/0	Range 33E	NMPM Lea	County	
Section 1	Townshi	p 145 Flumion (Show whet	her DF, RKB, RT, GR, etc.)	VI.		
	////////	41841	GR	Dilar Di	//////////////////////////////////////	
Cher	k Appropria	te Box to Indica	te Nature of Notice,	Report, or Other Da		
	NTENTION		SI SI	JBSEQUENT REP		
NOTICE OF I		, i i O.	-			
	PLUG	AND ABANDON	REMEDIAL WORK			
	CHAN	GE PLANS		COMMENCE DRILLING OPNS. L PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMPACTIONS & acid treatment X		
PULL OR ALTER CASING			CASING TEST AND			
12 Describe Proposed or Completed (Operations (Clearly	y state all pertinent deta	ils, and give pertinent dates,	including estimated date of sta	rring any proposed	
work) SEE RULE 1103.	1 miggod	up pulling ur	nit. Unseat pump	. TOOH with rods	. Unseat	
6-16-94 — Moved in tubing anchor. Str	and rigged	TOOH with D	oduction string.			
tubing anchor. Str	ip on BUr.	10011 wien p.	1 (D) (b) 16 /	0^{11} holes 9851-98	374' (Bough C)	
6-17-94 - WIH & per with 7 .40" holes a	torated 9/	53-5012 (D002)	w/7 .40" holes.	TIH w/7" packer	and RBP.	
with 7 .40" holes a Correlated into pla	ana 9943-990	BP at 9990'.	Tested to 1000 H	si. Pumped 100	parrels 2% KUL	
Correlated into pla down annulus. Rele	ace. Set K	r. Reset at	9929'. Could not	break perforati	ons 9942-9905 .	
down annulus. Rele Spot 1 barrel acid	aseu packe	forations 994	2-9963'. Broke a	at 600 psi. Acid	12ed peris.	
Spot 1 barrel acid 9942-9963' with 100	across per	15% NEFE acid	. Released pack	er and latched on	LO KDr.	
9942-9963' with 100 6-18-94 - Pulled up	n and set R	BP at 9890'.	Could not test	RBP. Released to	orid across	
6-18-94 - Pulled up changed tools. TIN	H and set R	BP at 9890'.	Tested to 500#.	Spot 5 Darreis	9874' with -	
				eriorations 9755		
perforations 9753- 5100 gallons 15% N	EFE acid.	Released pack	er and RBP	ring as follows:	bull plug,	
$6_{19}_{20}_{94} - TOOH$	with workst	ring. III wi	en promo	tubing, tubing an	chor & 300	
6-19-20-94 - TOOH 10' mud anchor, pe joints of tubing.	rforated su	ib, seating ni	ppie, 12 Joins	& rods. Release	d to production.	
isints of tubing.	Tubing and	mor set at be				
I hereby certify that the information abo	ove is true and comple	ete to the best of my known	cage and baller.		DATE	
SIGNATURE Kusty	Klin		Producti	lon Clerk	DATE 505-748-1471 TELEPHONE NO.	
SIGNATURE	- push-					
TYPE OR PRINT NAME RUSTY K	lein					
			Pa	. Signed by ul Kautz eologist	JUN 29 19	