## Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Marian and Natural Resources Department

Form C-103

..... ------

APPROVED BY -

Revised 1-1-89

\_ DATE --

District Office		ON DIVISION		
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO. 30-025-32188	
P.O. Box 1980, Hobbs, 14141 88240				
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexic	20 87504 2000	5. Indicate Type of Lease STATE	FEE XX
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	,		6. State Oil & Gas Lease No.	
•		UELL C	V/////////////////////////////////////	
( DO NOT USE THIS FORM FOR PE	FICES AND REPORTS ON WARDPOSALS TO DRILL OR TO DEEP PROVIR. USE "APPLICATION FOR C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement	Name	
1. Type of Well:			Childress AKV	
WELL XX WELL	OTHER		8. Well No.	
2. Name of Operator	OD A TIT ON		11	
YATES PETROLEUM CORPO	JRATION		9. Pool name or Wildcat LCC	2.7
3. Address of Operator  105 South Fourth Str	eet - Artesia, NM 882	10	Saunders Permo Upper	reliti
4. Well Location			Mag	† Line
Init Letter M : 99	90 Feet From The South	Line and330	Feet From The West	Line
One Zem.		22F	NMPM Lea .	County
Section 1	Township 14S	Range 33E sether DF, RKB, RT, GR, etc.)		777777777
	4184'	GR	\//////	
(//////////////////////////////////////	k Appropriate Box to Indic	ate Nature of Notice,	Report, or Other Data	
11. Chec	K Appropriate box to more	Sl	JBSEQUENT REPORT	OF:
NOTICE OF I	NTENTION TO:			()
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING (	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL	JNG OPNS. PLUG AND	ABANDONMENT L
_	7	CASING TEST AND	CEMENT JOB	
PULL OR ALTER CASING	٠.	X OTHER:		
OTHER: Add perforations				manased
12. Describe Proposed or Completed Cowork) SEE RULE 1103.	operations (Clearly state all pertinent de	uails, and give pertinent dates, i	ncluding estimated date of starting any	proposeu
CONTINUED:				
with scale inhibitor 8. Set RBP at 9835'	and ball sealers down to and test. Spot 1 bb to and test and test of the sealers down and ball sealers down to packer & RBP.	ns 9753-9812' with	ross perforations 9753 4000 gallons 15% NEFF	3-9812'. E acid
		•	•	-
				•
		·		
			·	
I hereby certify that the information above	ve is true and complete to the best of my know	wledge and belief.		6-1/-9/
Kustic	Their	mue _ Producti		6-14-94
SIGNATURE			505 TELEP	5-748-1471 HONE NO.
TYPE OR PRINT NAME RUSTY KI	Lein			
(This space for State Use)				JUN 20 19

RECENTER

. While

office