

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-34002
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	VA 996
7. Lease Name or Unit Agreement Name	ESTACADO 14 STATE
8. Well No.	1
9. Pool name or Wildcat	WILDCAT
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4097' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator RAND PAULSON OIL COMPANY, INC
3. Address of Operator 508 W. WALL, STE 100 MIDLAND TX 79701	4. Well Location Unit Letter G : 1980 Feet From The NORTH Line and 1980 Feet From The EAST Line Section 14 Township 14-S Range 34E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SPUD WELL @ 4:30PM 6-6-97. DRILLED 445' OF 17 1/2" OH. RAN 10 JTS 13 3/8" 48# H-40 STC & CEMENTED W/ 450 SX C + 2% CaCl₂. CIRC 75 SX TO SURFACE. DRILL 6200' OF 11" HOLE. RAN AND CEMENTED 8 5/8" 32 LBS K-55 & S-80 CASING IN 2 STAGES W/DV TOOL @ 4000'. 1ST STAGE: 500 SX 65:35 C:POZ + ADDITIVES AND 200 SX C NEAT. CIRC 100 SX OFF DV TOOL. 2ND STAGE: 1400 SX C + 3% SMS + 200 SX C NEAT TAIL. CIRC 140 SX TO SURFACE.

6-25-97 DRILLING 7 7/8" HOLE @ 8992'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE O. H. Routh TITLE AGENT DATE 6-26-97

TYPE OR PRINT NAME O. H. ROUTH TELEPHONE NO. 915-687-0323

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: