


YATES PETROLEUM CORPORATION
Indigo State Unit #1
Section 7-T12S-R35E
Lea County, New Mexico

SUNDRY NOTICE CONTINUED:

Perforate 12368-12386' (Morrow).

6. If the well does not flow or if there is no fluid entry, load tubing with 7% KCL water. Release packer and TOOH with tubing, packer and TCP guns.
7. Acidize and frac perforations 12368-12386' (Morrow) as necessary for production.
8. Swab/flow.
9. Release well to production to place into production.


Rusty Klein

Operations Technician
December 2, 2000