

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-5732	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Phillips Petroleum Company		Goldston-A
3. Address of Operator		9. Well No.
Room 711, Phillips Bldg., Odessa, Texas 79761		1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>south</u> LINE AND <u>660</u> FEET FROM		Undesignated
THE <u>east</u> LINE, SECTION <u>36</u> TOWNSHIP <u>5-S</u> RANGE <u>32-E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4439.6 DF		Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-18-72: COOH. Laid down DCs and fishing tools. Howco spotted cement plugs thru 4" DP as follows.

50 sx (100') from 1200' - 1100'.

75 sx (100') from 350' - 250'.

30 sx (40') from 40' - 0'.

Hole loaded w/9.8# mud between plugs. Released rig 3 PM, 9-18-72.

Welded on marker. Well P & A.

(This was an unsuccessful re-entry attempt of Goldston Oil Company's Lambirth State #1, originally drilled and abandoned in 1951.)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED	W. J. Mueller	TITLE	Senior Reservoir Engineer
DATE	9-19-72		
APPROVED BY	John W. Ransom	TITLE	
DATE			