## UNITED STATES SUBMIT IN TRIP CATE (Other instruction in redefence of the INTERIOR verse side)

Form approved.
Budget Bureau No. 42-K1424.
E DESIGNATION AND SERIAL NO.

•	LEAGE	•	DESIGNATION AND	
	NM	_	034546-B	

GEOLOGICAL SURVET	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill, or to deepen or plug, back, to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	
Use "APPLICATION FOR PERMIT—" for such propogais.)	7. UNIT AGREEMENT NAME
1.	I. CVII Adams.
OIL X GAS WELL OTHER	8. FARM OR LEASE NAME
2. NAME OF OPERATOR	
Western States Producing Company	Federal "24"
3. ADDRESS OF OPERATOR	9. WELL NO.
900 Building of the Southwest Midland, Texas 79	701 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.	10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface	Chaveroo
	11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA
1980' FNL & 660' FWL	
1980. LVF & 000 LMF	Sec. 24, T-9-S, R-32-E
14 PERMIT NO.   15, ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
14. FBRAIL NO.	Roosevelt New Mexico
4460 KB	
16. Check Appropriate Box To Indicate Nature of Notice, Report,	or Other Data
NOTICE OF INTENTION TO:	BSEQUENT REPORT OF:
DULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
TEST WATER SHUT-OFF	ALTERING CASING
FRACTURE TREAT  MULTIPLE COMPLETE  FRACTURE TREATMENT  APANDON*  SHOOTING OR ACIDIZING	
SHOOT OR ACIDIZE	
REPAIR WELL CHANGE PLANS (Other)	esults of multiple completion on Well
REPAIR WELL CHANGE PLANS (Other)  (Other)  (Other)	esults of multiple completion on Well completion Report and Log form.)
REPAIR WELL  (Other)  CHANGE PLANS  (Other)  (Note: Report recompletion or Report recomplet	esults of multiple completion on Well completion Report and Log form.) dates, including estimated date of starting any rertical depths for all markers and zones perti-
REPAIR WELL  (Other)  CHANGE PLANS  (Other)  (Other)  (Other)  (Other)  (Note: Report recompletion or Report recom	esults of multiple completion on Well completion Report and Log form.) dates, including estimated date of starting any rertical depths for all markers and zones perti-
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent of proposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000 in 4 1/2"  2. Shot 4 1/2" casing off @ 3100 on 3-19-69.	esults of multiple completion on Well completion Report and Log form.) dates, including estimated date of starting any rertical depths for all markers and zones perti-
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent proposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'	esults of multiple completion on Well completion Report and Log form.) dates, including estimated date of starting any rertical depths for all markers and zones perti-
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent proposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent proposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent proposed work. If well is directionally drilled, give subsurface locations and measured and true venent to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100'. on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent oproposed work. If well is directionally drilled, give subsurface locations and measured and true in nent to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent proposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent oproposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.  7. Commenced working 4 1/2" pipe on March 19, 1969.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent proposed work. If well is directionally drilled, give subsurface locations and measured and true versions to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent oproposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.  7. Commenced working 4 1/2" pipe on March 19, 1969.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent oproposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.  7. Commenced working 4 1/2" pipe on March 19, 1969.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent of proposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.  7. Commenced working 4 1/2" pipe on March 19, 1969.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent of proposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.  7. Commenced working 4 1/2" pipe on March 19, 1969.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent of proposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.  7. Commenced working 4 1/2" pipe on March 19, 1969.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent oproposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.  7. Commenced working 4 1/2" pipe on March 19, 1969.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent oproposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.  7. Commenced working 4 1/2" pipe on March 19, 1969.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent oproposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.  7. Commenced working 4 1/2" pipe on March 19, 1969.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL CHANGE PLANS (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent oproposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.  7. Commenced working 4 1/2" pipe on March 19, 1969.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent of proposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.  7. Commenced working 4 1/2" pipe on March 19, 1969.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent of proposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.  7. Commenced working 4 1/2" pipe on March 19, 1969.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)
REPAIR WELL (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent of proposed work. If well is directionally drilled, give subsurface locations and measured and true value to this work.)  1. Spotted 50 sacks Class H cement to 4,000' in 4 1/2"  2. Shot 4 1/2" casing off @ 3100', on 3-19-69.  3. Spotted 50 sacks cement plug from 3150' - 2870'  4. Spotted 50 sacks cement plug from 1880' - 1580'.  5. Spotted 10 sacks cement plug in top 10' surface pipe hole marker.  6. 1600' 4 1/2" casing left in hole.  7. Commenced working 4 1/2" pipe on March 19, 1969.	esults of multiple completion on Well recompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perticularly casing on 3-4-69 (aug.)

\*See Instructions on Reverse Side

TITLE \_

(This space for Federal or State office use)

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY

TITLE Production Engineer

APPROVEDATE

ACTING DISTRICT ENGINEER