	NITED STATES ART. NT OF THE INT	SUBMIT IN TPULIC (Other instru 6 o	Form approved. Budget Bureau No. 42-R1424.  5. LEASE DESIGNATION AND SERIAL NO.  NM 034546 - B  6. IF INDIAN, ALLOTTED OR TRISE NAME
SUNDRY (Do not use this form for Use "A	NOTICES AND REPORT proposals to drill of to deepen or persists.	S ON WELLS lug back to a different reservoir. sch proposals.)	10
1.  OIL X GAS WELL OTHER  2. NAME OF OPERATOR			8. FARM OR LEASE NAME
Southwestern Natural Gas, Inc.  3. ADDRESS OF OPERATOR  900 Bank of the Southwest Midland, Texas 79701			Federal 24
900 Bank of the Southwest Midland, Texas 79701  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface  1980 FNL, 660 FWL			Chaveroo  11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO.	15. BLEVATIONS (Show wheth	ner DF, RT, GR, etc.)	Sec. 30, T-7-S, R-33-E  12. COUNTY OF PARISH 18. STATE  ROOSEVELT New Meximum
16. Che	ck Appropriate Box To Indica		, or Other Data
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS  TED OPERATIONS (Clearly state all per directionally drilled, give subsurface	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZIN (Other) (NOTE: Report Completion or R	
7-29-68 Perforat 4245, 42 7-30-68 Acidized	ed as follows: 4133, 65, 4274, 4321, 4327, w/1,000 gals. Frace	4151, 4165, 4200, 4 4334, 4342, 4346, 4	exolibunten  light minites madity of simpling guiding the configuration of beorganic strongs if has professing to the following streams of the series of additions who appears to the following streams of the series of the model model of the series of the model model of the series of the model of the series of the model of the series of the series of the model of the series of th
81GNED SIGNED	ELITIZ TELLE	Office Manager	DATE 8/19/68
(This space for Federal or 8  APPROVED BY CONDITIONS OF APPROVA	TITLE	n	

\*See Instructions on Reverse Side

SE APROYED

GORDON

J L GORDON ACTING DISTRICT ENGINEER