

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JUL 3 12 22 PM '69

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Continental Oil Company	8. Farm or Lease Name George W. Lee
3. Address of Operator Box 460, Hobbs, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>22</u> TOWNSHIP <u>3-S</u> RANGE <u>32E</u> NMPM	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4305 DF	12. County Roswell

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work done; Drilled to 7956'. Ran Gamma Ray Sonic Caliper from T.D to 3221' and Gamma Ray from 3221' to surface. Set 50 sacks of class H cement from 7312' to 7138', 50 sacks from 6960' to 6785', 50 sacks from 6152' to 5977', 50 sacks from 3940' to 3765', 100 sacks w/2% CACL from 3396' to 3056' in and out of 8 5/8 casing, 50 sacks from 2183' to 2055' and set 10 sacks plug at surface. Erected Dry Hole Marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Robert Gault III TITLE Administrative Section Chief DATE 6-25-69

APPROVED BY John W. Runyan TITLE DATE 7-1-69

CONDITION OF APPROVAL, IF ANY: