

OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO 88240

March 25, 1971

Amoco Production Co.
Box 68
Hobbs, New Mexico

Gentlemen:

In checking our records we find that no reports have been submitted for your Methodist Home Foundation Well No. 1 located in Unit B of Section 30, T-5-S, R-34-E since December 22, 1970, at which time Form C-103 covering the 9 5/8" casing was approved.

Since the well has apparently been standing for 60 days or more with no further work having been reported, please submit Form C-103 covering any work done since December, 1970, and showing the present status of and future plans for it. Also, if drilling has been completed, please submit Form C-105 accompanied by logs and two copies of a notarized tabulated list of the deviation surveys.

Yours very truly,

OIL CONSERVATION COMMISSION

Joe D. Ramey
Supervisor, District 1

mc

C
O
P
Y

HOBBBS, NEW MEXICO 88540

1. The first step in the process of the investigation is to identify the problem or issue that needs to be addressed. This involves gathering information about the situation and determining the scope of the investigation.

1. The first of the three main parts of the report is a general introduction to the subject of the report. This part is divided into three sections: a general introduction to the subject of the report, a general introduction to the subject of the report, and a general introduction to the subject of the report.

Journal of Management Education 30(6)p. 789-804
© The Author(s) 2006. Reprints and permissions:
<http://www.sagepub.com/journalsPermissions.nav>

143441 100 100 100 100 100

1956-1957 90°