

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>DRY HOLE</u>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator <u>AMOCO PRODUCTION COMPANY</u>	5. State Oil & Gas Lease No.
3. Address of Operator <u>P.O. DRAWER A, LEVELLAND, TEXAS 79336</u>	7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>NORTH</u> LINE AND <u>660</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>29</u> TOWNSHIP <u>5-S</u> RANGE <u>33-E</u> NMPM.	8. Farm or Lease Name <u>PETERSON "B"</u>
	9. Well No. <u>1</u>
	10. Field and Pool, or Wildcat <u>PETERSON PENN-ASSOC.</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4392' RDB</u>	12. County <u>ROOSEVELT</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

On 2/10/76 OC service unit and ran retrievable bridge plug and set at 7500' & cap with 35' cement. Pick up tlg. and spot 25 sx cement plug 7241'-7141'. Shot 5 1/2" csg at 4982' but unable to pick up. Shot csg at 5409' and unable to pick up. Spot 25 sx cement plug 6566'-6466', spot 35 sx cement plug 4036'-3936', spot 35 sx cement plug 4400'-4300', shot csg at 3900' and pick up 5 1/2" csg. Spot 35 sx cement plug 3525'-3425' across csg stub. Spot 35 sx cement plug 1700'-1600'. Spot 10 sx cement plug at surface and set PxA marker. Job complete 2/13/76.

TD-7845'

PRD-7377'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Ray W. Cox</u>	TITLE <u>Administrative Assistant</u>	DATE <u>9/21/76</u>
APPROVED BY <u>John W. Ramsey</u>	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY: 0:12 NMCC-H 1-DIV 1-Susp 1-RC		