October 3, 1974

Inspected the Leede and Pine, Stephens Well #1, located 1980/E and 1980/S in Section 19, Township 2 South, Range 35 East, on October 2, 1974. Reason for inspection was that Leede and Pine indicated they intended to re-enter the well in order to salvage pipe.

This well was originally inspected in October 1973 and the location was in good shape and I signed the final C-103.

Present inspection found the marker had been removed and cellar dug out, the dirt from the cellar was used to make a dike around the well one foot high and  $12' \times 12'$  in size. The dike was full of water to the top and bubbles were coming out of the cellar. This well is leaking slowly. A sample of water was taken and an analysis of same found it to contain 3493 ppm Cl.

Well has apparently been re-entered, but Leede and Pine has not filed a C-103 showing re-entry.

John W. Runyan New Mexico Oil Conservation Commission Geologist