67
RECEIVED AND THEFE
1.71
F. z
1.5 G.4.
CAND DEFICE
CHELATON .

COHEN WELLS STATE

## CIL CONSERVATION DIVISION

F .: =	0-1	7				
Err	525	٠.	-	:	7	

2.1	P 0. 80)	x 2008	Edm (C-1) 3 Emm Sec. 1 1 - 75
	SANTA FE, NEW	MEXICO 87501	Pot and SEX Control of
7			Sa. Liak ste Type of Let e
U.S. O.S.			State Ten X
CARDITICE			5. State Oil & Gas Lease No.
POTENTON			
and the second of the second o			
SERERY P	NOTICES AND REPORTS ON ALS TO DRIVE WAS CARD FOR THE PLANT OF TRANSPORTED TO THE PLANT OF THE PL	WELLS	
QEE TATROL ATION	TOR BEACHT IN FRANCE CATOLIACT SHE	TO A DOTE SACE.	17. Unit Agreenent Home
OIL GAS	75 * 7 7 7	3. '7 11 D 1 . 1 1	
		ole oilwell-Produced onl	y   8. Form or Lease Name
, Transpot Operator	salty formation v	vater.	
William K. Young			D. B. Lieb "A"
			3
750 West Fifth St., Ft. V	Worth, Texas 76102		1 10. Field and Pool, c Wildeat
, Location of Well			16. Filera and Foot, C. Bridea
1980	South	LINE AND660 FEET FROM	Wildcat
UNIT CELLEN			
Foot	32 TOWNSHIP 3-5	RANGE 33-E HMPM	
THE EAST CINE, SECTION			ATTITUTE TO SEE SEE SEE SEE SEE SEE SEE SEE SEE SE
THE THE THE THE	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County (////////
	4297 GR		Roosevelt
		Sature of Notice, Report or O:	
		enaseonen	T REPORT OF:
NOTICE OF INTE	ENTION TO:	30030000	THE SKI ST.
	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
HADW DAIC MAR MANNING	PEDS AND VEXABOUR (X)	COMMENCE DEILLING OPHS.	PLUG AND ABANDONMENT
TEMPCRARILY ARANDON	[ <del></del>	[	(
TULL OR ALTER CABING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	
OTHER			
17. Describe Proposed or Completed Opera	tions (Clearly state all pertinent det	ails, and give pertinent dates, includir.	g estimated date of starting any proposed
17. Describe Proposed of Completed Chero work) 55% RULE 1103.	tions (S. com) orași en primeir - en		
Well has been temporarily	_	-77 (See Form C-105 date	d 2 <b>-</b> 16-78). Propose to
P & A as follows: PRTD	3740. Perfs 3680-90'		

- Set cast iron bridge plug @3675±, cap w/35' cmt. Load hole w/10# gel mud.
  Free point 5" csg. Cut csg. approx. 2500', spot 100' cmt. plug (50' inside and 50' outside) 5" stub. Cmt. plug to be tagged.
- If cut 5" below base of salt at 2400' spot 100' cmt. plug @2400' cmt. plug to be tagged.

4.	is set @1719'. Cmt. plug to	low and 50° up into 8 5/8° csg. whi o be tagged.	.cn·		
5.	Spot 10 sacks at surface from				
6.		well giving Well Name, Company, Leg	al		
	Description, County.		•		
	Notify Oil Conservation Com	mission 24 hrs. prior to commencing	gopera	ations.	
	•				
	y that the information above is true and comple	to to the best of my knowledge and belief.			
is. I hereby certify	y that the information above is true and comple	te to the best of the distance of the second			
*15 N CO	E. Mortimery	TITLE	DATE_	_10-5-82	
				007 ~	4000
APPROVED BY	eright of	TITLE	DATE	OCT 7	1982
CONDITIONS OF	APPROVAL FAMI				