

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20523
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Lambirth
8. Well No. 9
9. Pool name or Wildcat South Peterson Fusselman

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator EP Operating Company	
3. Address of Operator 6 Desta Drive, Suite 5250, Midland, TX 79705-5510	
4. Well Location Unit Letter <u>P</u> : <u>560</u> Feet From The <u>South</u> Line and <u>560</u> Feet From The <u>East</u> Line Section <u>25</u> Township <u>5S</u> Range <u>32E</u> NMPM <u>Roosevelt</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4368.4' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Casing was found to be collapsed from 6533'-54'. The tubing was backed off @ 6497'. Fishing attempts were unsuccessful. Verbal approval was obtained to perforate @ 6450'. A 5½" retainer was set at 6400'. The perforations were squeezed w/100 sx. Class C Neat to 1850#. 35' of cement was dumped on retainer and the well was temporarily abandoned 10/20/90. Plans are to plug and abandon well as follows:

Circulate hole w/mud laden fluid.

Lay 20 sk. cement plug from 3048'-148' (50' above & below top of San Andres).

Cut 5½" casing @ 2050' and lay casing down.

Lay 60 sk. cement plug from 2000'-117' (50' below intermediate shoe in 5½" casing & 50' above 5½" casing stub inside 9-5/8" casing).

Tag plug.

Lay 40 sk. cement plug inside 9-5/8" casing from 1700'-1800'.

Lay 10 sk. surface plug.

Cut off casinghead and weld on steel plate. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE S. D. Reed TITLE Production Superintendent DATE 11/8/91

TYPE OR PRINT NAME S. D. Reed (915) 682-9756 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSIONER OF THE STATE OF NEW MEXICO
OFFICE OF THE COMMISSIONER
SANTA FE, NEW MEXICO 87504-2088