State of New Mexico **Submit 3 Copies** Form C-103 to Appropriate District Office 1 Ly, Minerals and Natural Resources Departmen. Revised 1-1-89 DISTRICT OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 WELL API NO. P.O. Box 2088 30-041-20525 DISTRICT Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease FEE X STATE __ 1000 Rio Brazos Rd., Aziec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Lambirth A 1. Type of Well: METT GY? WELL X OTHER 2. Name of Operator 1. Well No. Phillips Petroleum Company 5 3. Address of Operator 9. Pool name or Wildow 4001 Penbrook Street Peterson, South (Penn) Assod. 4. Well Location 660' 660' South Unit Letter Feet From The West Line and Feet From The Line Section 30 T-5-S 33-E Township Range Roosevelt **NMPM** County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4376' GL, 4392' **RKB** Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. MI DU. - Freepoint 2-7/8" tubing and clean out well to 7600'. Set 5.5" CIBP at 7600' with 2-3/8" N-80" workstring. Circulate well with 2. 9.5 ppg mud-laden fluid. Spot Plug No. 1 (25 sx. cement) 7500' - 7600'. Covers Delaware. 3. Spot Plug No. 2 (25 sx. cement) 6390' - 6490'. Covers Abo. 4. Perforate and squeeze with Plug No. 3 (50 sx. cement) 4214' - 4314'. Covers Glorietta. (Over) I hereby cartify that the information above is true and complete to the best of my knowledge and belief SIGNATURE ___ DATE ____12-20-93 Ma Supervisor, Regulatory

TYPE OR FRANT NAME

L.M. Sanders

Orig. Signed by Paul Kautz

TITLE

DATE

THE COMMISSION MUST BE NOTIFIED 24

AFTROVED BY

HOURS IN THE PROPERTY OF THE P

Geologist

- 5. Freepoint 5-1/2" casing. Need to pull 3550'
- 6. Spot Plug No. 4 (50 sx, cement) 3450 3550 Tag plug, Cover 8-5/8" casing seat.
- 7. Spot Plug No. 5 (35 sx. cement) 2980' 3080'. Covers the San Andres.
- 8. Spot Plug No. 6 (35 sx. cement) 1957' 2057'. Covers the Yates.
- 9. Spot Plug No. 7 (110 sx. cement) 3' 407'. Covers the 13-3/8" casing seat and surface plug.
- 10. Cut off casing 3' below ground level. Install monument marker and perform reclamation work.