---711 2 0143 E17 V M 11 O 14 D 1 V 1 3 1 0 1 4 DISTRIBUTION P. O. BOX 2088 SANTA FE SANTA FE, NEW MEXICO 87501 1 16 U.3.G.3.

LAND OFFICE DACRATOR

ame of Operator

darees of Operator

ocation of rail

2)

3)

P.O. Drawer 2437,

WELL X

__н____.__1874

_ LIME, SECTION ____

NOTICE OF INTENTION TO:

BHP Petroleum (Americas), Inc

P. O. BOX 2088 SANTA FE, NEW MEXICO 87501	Form C-103 - Revised 10-1-78
	State Cli & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
X 07HER-	7. Unit Agreement Name
	8. Farm or Lease Name
Americas), Inc.	Bledsoe
, Midland, Texas 79702	9. Well No.
	10. Fleid and Pool, or Wildcat
INE. SECTION 11 TOWNSHIP 6-S RANGE 33-E NAME.	South Peterson Penn Assoc
15. Elevation (Show whether DF, RT, GR, etc.) 4402.3 GR	12. County Roosevelt
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	ner Data REPORT OF:
PLUG AND ABANDON X REMEDIAL WORK COMMENCE DRILLING OPMS. CHANGE PLANS CASING TEST AND CEMENT JOB OTHER	ALTERING CASING PLUG AND ABANDONMENT

Donctibe Proposed of Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any proposes WORK) SEE RULE 1103.

- 1) See attached "Completion Data Sheet" for well schematic.
 - These plugging operations are expected to commence in January, 1986.

SUNDRY NOTICES AND REPORTS ON WELLS
S FORM FOR PROPOSALS TO DAILL OF TO DEEPEN OF PLUE BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" IFORM C-101) FOR SUCH PROPOSALS.)

- We propose to plug and abandon the well as follows:
- Set a CIBP at approximately 7500' w/3 sx of cmt on top. a)
- b) Load hole with 10# salt gel.
- c) Spot 25 sx cmt across top of Abo at 6490'.
- d) Shoot off csg above cmt plug at approximately 6000', and pull csg. from well.
- e) Spot 25 sx cmt across top of cut-off casing at 6000'. Leave 1/2 in and 1/2 out.

Michael L. Jones	Petroleum Engineer	DATE 12/19/85
	nd complete to the best of my knowledge and belief.	
	THE COMMISSION FOR THE PART HOURS PREDICTOR OF THE MOST PAUSICING CERTINATORS FOR THE TO DE MIRROYED.	
h) Spot 10 sx cmt plug at.i) Weld on NMOCC approved	P&A marker.	