

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐  
Name of Operator  
Phillips Petroleum Company  
Address of Operator  
Rm. 401, 4001 Penbrook, Odessa, Texas 79762  
Location of Well  
UNIT LETTER M 660 FEET FROM THE south LINE AND 510 FEET FROM  
THE west LINE, SECTION 29 TOWNSHIP 5-S RANGE 33-E NMPM.

7. Unit Agreement Name  
-----  
8. Farm or Lease Name  
Peterson H  
9. Well No.  
1  
10. Field and Pool, or Wildcat  
Peterson Penn South  
12. County  
Roosevelt

15. Elevation (Show whether DF, RT, GR, etc.)  
4371' GR, 4384.3' RKB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER Propose to complete in the Wolfcamp (Hueco-Todd) as SWD. ☒

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well presently shut in (Perfs 7332- 7341').

Propose converting well to SWD in the Wolfcamp (Hueco-Todd) formation.

Administrative approval requested by separate letter dated April 9, 1981.

Procedure as follows:

1. RU DD unit. Install BOP.
2. Pull and lay down tbg. and pkr.
3. Run Salta lined 2-7/8", 6.5#, J-55 tubing and Baker Lok-Set pkr. open ended at + 7300'.
4. Prior to setting pkr, reverse annulus w/120 bbls of produced water w/inhibitor.
5. Set pkr.
6. Install wellhead inj equipment and start injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W.J. Mueller

TITLE Sr. Engineering Specialist

DATE April 10, 1981

Or, Signed by

Jerry Barton

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: