o Appropriate District Office	Energy, M	ew Mexico Iral Resources Department		Form C-103 Revised 1-1-89
	OIL CONSERVA	TION DIVISION	WELL API NO.	
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088			30-041-20565	
Santa Fe, New Mexico 87504-2088 2.0. Drawer DD, Anesia, NM 88210			5. Indicate Type of Lease STATE FEE X	
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease	No.
( DO NOT USE THIS FORM FOR PR	ICES AND REPORTS ON OPOSALS TO DRILL OR TO DI RVOIR. USE "APPLICATION FO C-101) FOR SUCH PROPOSALS	OR PERMIT"	7. Lease Name or Unit Ag	greement Name
1. Type of Well: OIL OAS WELL X WELL	OTHER		Pearl Jordan	
2 Name of Operator	lortnorchip		8. Well No. 2	
EP Operating Limited Partnership		9. Pool name or Wildcat		
. Address of Operator 6 Desta Drive, Suite 5250, Midland, TX 79705-5510			North Peterson Penn.	
4 Wall Logation	980 Feet From The South		60 Feet From The	East Line
Unit Letter :		Barra 33E	Rooseve	1t County
Section 17	Township 4S	Range 335E whether DF, RKB, RT, GR, etc.)	NMPM ROOSEVE	
	10. Elevation (Snow	4396.9' GR		
		licate Nature of Notice, I	Report, or Other Dat	a
	TENTION TO:	SU	BSEQUENT REPO	DRT OF:
NOTICE OF IN				
	PLUG AND ABANDON			
	CHANGE PLANS			
PULL OR ALTER CASING		CASING TEST AND		
other:		OTHER:		
12. Describe Proposed or Completed Op- work) SEE RULE 1103.		details, and give pertinent dates, inc	luding estimated date of start	ing any proposed
Work performed from 4 Attempted to pull rod rods leaving 83 rods hole w/rods and screw could not release TAC screwed back together 96 rods in hole. Ran w/string shot, fired ing collar @ 5693', f off @ 5662', did not fish @ 5701'. Attempt above top of fish. RU cement w/2% CaCl, slu water. WOC. Tested pl Ihereby certify that the information above in	s. Worked 4 hrs., u and pump in hole. A ed rods back togeth . Pumped 180 BW dow . Stuck rods 25' at free point. Set dow shot, tubing did no ired shot, tubing di lose any torque. H ted to jar fish loos J Halliburton and pu arry weight 15.6#/ga Lug to 300# for 15 n	ttempted to pull to ner. Could not unsea on casing, 40 BW dow oove fish, unable to on on fish @ 5741'. ot back off. RIH w/2 hid not back off. RI RIH w/chemical cutte se w/no success. RIN umped 15 bbls. fresh al., slurry volume of nins.(test witnessed owkedge and belief.	t pump. Attempter m tubing, did no go back down. D Found tubing fro 00 grain string H w/string shot er, cut 2-3/8" to w/tubing open h water followed bbls. Flushed by State). Ran	ods. Recovered 241 release TAC. Ran ed to pull tubing, ot load. RIH w/rods Backed off rods. La ee @ 5730'. POH, R shot. Set over tu #3. Attempted bac ubing @ 5703'. Top ended to 5681', 20 by 200 sacks Clas w/15 bbls. fresh tubing to 5681'.
Attempted to pull rod rods leaving 83 rods hole w/rods and screw could not release TAC screwed back together 96 rods in hole. Ran w/string shot, fired ing collar @ 5693', f off @ 5662', did not fish @ 5701'. Attempt above top of fish. RU cement w/2% CaCl, slu water. WOC. Tested pl I hereby certify that the information above is skonature	s. Worked 4 hrs., u and pump in hole. A red rods back togeth . Pumped 180 BW dow . Stuck rods 25' ak free point. Set dow shot, tubing did no ired shot, tubing di lose any torque. H red to jar fish loos Halliburton and pu nrry weight 15.6#/ga Lug to 300# for 15 m	trempted to pull to ner. Could not unsea on casing, 40 BW dow oove fish, unable to on on fish @ 5741'. ot back off. RIH w/2 hid not back off. RI RIH w/chemical cutto se w/no success. RII umped 15 bbls. frest al., slurry volume nins.(test witnessed owledge and belief.	t pump. Attempter n tubing, did no go back down. I Found tubing fro 00 grain string H w/string shot er, cut 2-3/8" to 1 w/tubing open n water followed 2 bbls. Flushed 1 by State). Ran	ods. Recovered 241 release TAC. Ran ed to pull tubing, ot load. RIH w/rod Backed off rods. L ee @ 5730'. POH, R shot. Set over tu #3. Attempted bac ubing @ 5703'. Top ended to 5681', 20 by 200 sacks Clas w/15 bbls. fresh tubing to 5681'.
Attempted to pull rod rods leaving 83 rods hole w/rods and screw could not release TAC screwed back together 96 rods in hole. Ran w/string shot, fired ing collar @ 5693', f off @ 5662', did not fish @ 5701'. Attempt above top of fish. RU cement w/2% CaCl, slu water. WOC. Tested pl I hereby certify that the information above is skONATURE	s. Worked 4 hrs., u and pump in hole. A ed rods back togeth . Pumped 180 BW dow . Stuck rods 25' at free point. Set dow shot, tubing did no ired shot, tubing di lose any torque. H ted to jar fish loos J Halliburton and pu arry weight 15.6#/ga Lug to 300# for 15 n	trempted to pull to ner. Could not unsea on casing, 40 BW dow oove fish, unable to on on fish @ 5741'. ot back off. RIH w/2 hid not back off. RI RIH w/chemical cutto se w/no success. RII umped 15 bbls. frest al., slurry volume nins.(test witnessed owledge and belief.	t pump. Attempter m tubing, did no go back down. D Found tubing fro 00 grain string H w/string shot er, cut 2-3/8" to w/tubing open h water followed bbls. Flushed by State). Ran	ods. Recovered 241 release TAC. Ran ed to pull tubing, ot load. RIH w/rods Backed off rods. Lo ee @ 5730'. POH, R shot. Set over tu #3. Attempted bac ubing @ 5703'. Top ended to 5681', 20 by 200 sacks Clas w/15 bbls. fresh tubing to 5681'.

^

CONDITIONS OF APPROVAL, IF ANY:	