

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator EP Operating Company	8. Farm or Lease Name LaGrone
3. Address of Operator 6 Desta Drive, Suite 5250, Midland, Texas 79705-5510	9. Well No. 1
4. Location of Well UNIT LETTER <u>H</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>510</u> FEET FROM THE <u>East</u> LINE, SECTION <u>29</u> TOWNSHIP <u>4S</u> RANGE <u>33E</u> NMPM.	10. Field and Pool, or Wildcat Dora, North (Penn)
15. Elevation (Show whether DF, RT, GR, etc.) 4359.2' GR	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP at 7645'. Circulated hole with 9.5# mud. Spotted 5 sacks Class "C" cement on top of CIBP at 7645'. Cut off 5-1/2" casing at 2921' and pulled 71 joints casing. Spotted 30 sacks Class "C" cement plug at 5016'. Spotted 60 sacks Class "C" cement plug at 2971'. Tagged top of plug at 2833'. Spotted 60 sacks Class "C" cement plug at 2012'. Tagged plug at 1850'. Pumped 15 sacks cement for surface plug. Cut off casinghead and welded on steel plate. Installed dry hole marker. P&A 4/18/88.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>A. J. Reed</u>	TITLE <u>Production Superintendent</u>	DATE <u>4/25/88</u>
APPROVED BY <u>Jack Griffin</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>AUG 16 1988</u>
CONDITIONS OF APPROVAL, IF ANY:		

