

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

1a. Indicate Type of Lease
State ☒ For ☐

5. State Oil & Gas Lease No.
LG1296

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Energy Reserves Group, Inc.	8. Farm or Lease Name El Paso State
3. Address of Operator P. O. Drawer 2437, Midland, Texas 79702	9. Well No. 3
4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 8 TOWNSHIP 6-S RANGE 34-E NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 4363.9 GL	12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

09-08-81 TD 7900' Finished TIH w/4 1/2" DP open ended to 7756' and spot 40 sax Class "H". LD DP to 7286' & spot 50 sax Class "H". LD DP to 6575' & spot 50 sax. Class "H". LD DP to 4496' and spot 170 sax Class "H". LD DP to 3370' & spot 40 sax Class "H". LD DP to 1000' & spot 30 sax Class "H". Will install dry hole marker & 10' plug @ surface after moving rig. Release rig @ 8:00 P.M. on 09-07-81.

09-09-81 TD 7900'. Stack rig. Spot 10' plug of Class "H" @ surface w/dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *R. L. Robertson* **R. L. Robertson** TITLE Production Engineer II DATE 09-09-81

APPROVED BY *A. H. Stettin* TITLE OIL & GAS INSPECTOR DATE MAY 25 1982

CONDITIONS OF APPROVAL, IF ANY: