

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-041-20632
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER ☐
2. Name of Operator
H. L. Brown, Jr.
3. Address of Operator
P.O. Box 2237, Midland, Texas 79702-2237
4. Well Location

7. Lease Name or Unit Agreement Name
VLS
8. Well No.
1
9. Pool name or Wildcat
S. Peterson (Penn)

Unit Letter P : 660 Feet From The East Line and 1300 Feet From The South Line
Section 11 Township 6S Range 33E NMPM Roosevelt County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4383.8' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Currently Have: 17 1/2" Hole w/ 13-3/8" csg @412'. Cmt'd to surface.
11" Hole w/ 8-5/8" csg @3397'. Cmt'd to surface.
7 7/8" Hole w/ 5-1/2" csg @7800'. Cmt'd w/ 832 SX.
Perfs: 7756 - 7788'.

Plug as follows: CIBP @ ± 7700'. Cap w/150' cmt.
Freepoint, cut & retrieve 5 1/2" csg. Spot 150' cmt @cutoff.
Tag cmt plug. Spot 150' cmt plug 4347'-4497' @Glorieta (4423').
Spot 140' cmt plug @3327'-3467' @ 8-5/8" shoe.
Tag cmt plug. Spot 120' cmt plug @2130'-2250' @ top of salt (2190').
Spot 10 SK surface plug. Cut off 3' underground.
Weld on P&A plate and marker. Restore location.

I hereby certify that the information above is true, and complete to the best of my knowledge and belief.

SIGNATURE

TYPE OR PRINT NAME

TITLE

DATE

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

MAR 04 1994

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.