

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

## L CONSERVATION DIVISIC

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Energy Reserves Group, Inc. 3. Address of Operator P. O. Drawer 2437, Midland, Tx. 79702 4. Location of Well UNIT LETTER K, 2000 FEET FROM THE S LINE AND 1900 FEET FROM THE W LINE, SECTION 10 TOWNSHIP 6-S RANGE 33-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4385.7 GL	7. Unit Agreement Name 8. Farm or Lease Name McClellan 9. Well No. 1 10. Field and Pool, or Wildcat S. Peterson Fusselman 12. County Roosevelt
---	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 11" hole 6/27/84

6/29/84 Depth 2030'. Ran 51 jts of 8 5/8", 24#, J-55, ST&amp;C &amp; set @ 2034.94, cmt'd w/450 sx HLC &amp; tail in w/200 sx "C" neat. Circ 140 sx. WOC 18 hrs &amp; press BOP &amp; csg to 800# for 20 min.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R.L. Robertson R.L. Robertson TITLE Production Engineer III DATE 8/6/84ORIGINAL SIGNED BY JERRY DEATON  
DISTRICT I SUPERVISORAPPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE AUG 17 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 16 1984

O.C.D.  
HOBBS OFFICE