STATE OF NEW MINERALS DI		_	NT
40. 07 COPICS ACCTIVES	7		
DISTRIBUTION			
BANTAPE			
FILL			Ì
U.S.G.S.			
LAND OFFICE			
CRESATOR		1	1

AD, BY COPIES RECEIVED	C CON		TION DIVISION		Fa	c 101
DISTRIBUTION	P. O. BOX 2088		Form C-103 Revised 10-1-78			
BANTA PE	SANTA	FE, NEW	MEXICO 87501			
FILL	<del></del>				5a. Indicate Type of Lease	
LAND OFFICE					State	Fee X
OPERATOR					5. State Oil & Gus Leaso I	No.
					<u> </u>	
	SUNDRY NOTICES AND REF	PORTS ON	WELLS			
(DO NOT USE THIS FORM USE "A	SUNDRY NOTICES AND REF	PEN OR PLUG B	ACK TO A DIFFERENT RESERVO: H PROPOSALS.)	IR.		
1.					7. Unit Agreement Name	
OIL X WELL	OTHER-					
2. Name of Operator					8. Farm or Lease Name	
L & B Oil Compar	ny Inc				Tucker	
3. Address of Operator	ly, Inc.	<del></del>			9. Well No.	
, -	kway, Ste. 900 Houst	on Tex	ne 77036		1	
	kway, Ste. 900 House	on, rexe	13 77030		10. Field and Pool, or Wile	dcat
4. Location of Well	660	North	660		Wildcat	
UNIT LETTERD	660 FEET FROM THE	NOTEH	LINE AND	FEET FROM	MIIICAE	mm
1						
West Line	E, SECTION TOWNSH	4-5	RANGE	NMPM.		
						HH17.
			DF, RT, GR, etc.)		12. County	
	4314' (	GR			Roosevelt	777777
16.	Theck Appropriate Box To	Indicate N	ature of Notice Repo	ort or Oth	er Data	
	• • •	indicate iv			REPORT OF:	
NOTICE	OF INTENTION TO:	:	500	SEQUENT	REPORT OF.	
_		<u>ਦਿੱ</u>		$\Box$		
PERFORM REMEDIAL WORK	PLUG AND A	ABANDON [X]	REMEDIAL WORK	片	ALTERING CASIN	==
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.		PLUG AND ABAND	ONMENT [X
PULL OR ALTER CASING	CHANGE PL	ANS	CASING TEST AND CEMENT JO	18 <u> </u>		
•			OTHER			
OTHER	·	LJ :				
					antimated data of starting of	ne proposed
17. Describe Proposed or Comp work) SEE RULE 1103.	oleted Operations (Clearly state all	pertinent aet	ilis, and give pertinent autes	s, including	estimated date of starting d	my proposed
<i>wyn</i> , 522 // 522 - 775						
TD 7326'						
P & A Began p	lugging operations on	2-13-85	and completed ope	rations	at 7 a.m., 2-14-	-85.
1 0 11 1 10 11	. 33 0 1		_			
Plug l	7226' to 7326' w/ 35	5 sx. of	Class "C"			
Plug 2	6367' to 6467' "	11 11	H			
Plug 3	3640' to 3740' "	11 11	11			
_	3000' to 3100' "	11 11	***			
Plug 4	1450' to 1550' "	11 11	11			
Plug 5			11			
Plug 6		SA.	!!!!!			
Plug 7	Surface to 10' w/	o sx. CI	ass C			
-			•			
18. I hereby certify that the info	ormation above is true and complete	to the best	of my knowledge and belief.			
<u> </u>	0					
1 Julia 1	hand -		Engineering Assist	ant	DATE 3-1-85	
DIGHED LANGE	· urumox	TITLE	DIGTHEETING ASSIST		DATE	
	7 ~					
~ ( ) <sub>-</sub>	6 00	Chi	& GAS MOPEC	TOR		•
1000	X MILLER	The Contract of the Party of th			DATE	