

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

- CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- <u>PXA</u>	7. Unit Agreement Name
2. Name of Operator <u>AMOCO PRODUCTION COMPANY</u>	8. Farm or Lease Name <u>Skilbanks</u>
3. Address of Operator <u>P.O. BOX 68, HOBBS, NEW MEXICO 88240</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>C</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>West</u> LINE, SECTION <u>19</u> TOWNSHIP <u>5-S</u> RANGE <u>33-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Peterson Fusselman</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4419.1' GR</u>	12. County <u>Roosevelt</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon well as follows: MISU and Kill well x fresh water. POH x rods, pump, x tubing. RIH x 5 1/2" Cast iron bridge plug x set at 7600'. Spot 25 st Class H Heat Cement on top of bridge plug to 7380' (to cover top of Penn formation). Displace hole x 9 #/gal gelled brine from 7380' to surface. Spot 25 st Class C Heat from 5200' to 4950'. Spot 25 st Class C Heat from 3200' to 2950' (to cover top of San Andres formation). Spot 25 st of Class C Heat from 2200' to 1950' (to cover top of Yates formation). (over)

0+5: NMOCD-HOBBS; 1-J.R.BARNETT HOU RM. 21.156; 1-F.J.NASH HOU RM. 4.206; 1-BAO

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Beverly A. Ottwell TITLE SR. ADMINISTRATIVE ANALYST DATE 3-27-86

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____

TITLE _____

DATE APR 1 - 1986

CONDITIONS OF APPROVAL, IF ANY:

PX A Grilanka #1 (Continued)

Spot 25 at of Class 2 Great Cement from
1100' to 850' (to cover top of cat). Spot 5 at
Class 2 Great Cement from 50' to surface. MDS4 x
Remove wellhead x install plugged and
Abandoned marker.

RECEIVED
MAR 31 1986
HOBBS OFFICE