

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CEASE OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- <u>Dry PxA</u>	7. Unit Agreement Name
2. Name of Operator <u>AMOCO PRODUCTION COMPANY</u>	8. Farm or Lease Name <u>Peterson "A"</u>
3. Address of Operator <u>P.O. BOX 68, HOBBS, NEW MEXICO 88240</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>19</u> TOWNSHIP <u>5-S</u> RANGE <u>33-E</u> N.M.P.M.	10. Field and Pool, or Wildcat <u>Peterson Gussleman</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4418' RDB</u>	12. County <u>Roosevelt</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MISU 2-11-86. POH w/tubing x RIH w/cast iron bridge plug. Set CIBP at 7600'. Ran tubing to 7600' x displaced hole w/mud. Spotted 10 sp Cement on top of Bridge plug. Pulled tubing up in hole to 6500' x spotted 25 sp Class H Cement plug 6500'-6300'. Pulled tubing up in hole x spotted 46 barrels of 10# brine w/25# gel per barrel. POH w/tubing x RIH w/3 1/8" csg. gun. Perforated 4400'-4401' w/4 JSPF. RIH w/cement retainer x set at 4300. Squeezed perfs 4400'-4401' w/40 sp. Class H Cement. Pulled up in hole w/tub. x spotted 20 bbls 10# brine gel. Perforated 3510'-11' w/4 JSPF. RIH w/cement retainer x set at 3200'. Squeezed perfs w/125 sp Class H. Cement. String out x dumped excess Cement. Pulled tubing up in hole x spotted 66 barrels 10# brine gel. Perforated 500'-501' w/4 JSPF. Pumped 250 sp Class H neat Cement x circulated to surface. Left full to surface. Capped well x erected plugged and abandoned marker. MOSU 2-17-86.

O+5: NMOC-D-HOBBS; 1-J.R.BARNETT HOU RM. 21.156; 1-F.J.NASH HOU RM. 4.206; 1-BAO

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Beverly A. Ottwell TITLE SR. ADMINISTRATIVE ANALYST DATE 2-18-86
APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE MAR 2 1986
CONDITIONS OF APPROVAL, IF ANY: