

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b>	7. Unit Agreement Name
2. Name of Operator <b>Marshall Pipe &amp; Supply Co.,</b>	8. Farm or Lease Name <b>Stoltenberg</b>
3. Address of Operator <b>13423 Forestway Dr., Dallas, Texas 75240</b>	9. Well No. <b>#1</b>
4. Location of Well UNIT LETTER <b>F</b> <b>1650</b> FEET FROM THE <b>North</b> LINE AND <b>2310</b> FEET FROM THE <b>West</b> LINE, SECTION <b>26</b> TOWNSHIP <b>2S</b> RANGE <b>29E</b> NMPM.	10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4394 Ground Level</b>	12. County <b>Roosevelt</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**PLUGGING OPERATIONS: December 15th, 1986**

Plug #1 Hole size 7-7/8" Formation: Montoya Depth: 7290 to 7190  
35 sacks cement

Plug #2 Hole size 7-7/8" Formation: Abo " 5250 to 5350  
35 sacks cement

Plug #3 Hole size 7-7/8" Formation: Gloriata " 3100 to 3200  
35 sacks cement

Plug #4 inside 8-5/8", 50' plug from 2078 100' plug inside/outside  
hole size 7-7/8" 50' plug to 2178' 8-5/8" Casing  
35 sacks cement

Plug #5 Top of 8-5/8", 10 sacks cement  
Put one piece of 4-1/2" casing 2" down in  
8-5/8" Casing and 5' above ground

Sign on plate to weld on 4-1/2" Casing:

**MARSHALL PIPE & SUPPLY COMPANY**  
**STOLTENBERG #1**  
**Sec 26-2S, 29E**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. W. Marshall TITLE Operator DATE 12-18-86

APPROVED BY J. W. Marshall TITLE DISTRICT 1 SUPERVISOR DATE JAN 12 1987

ORIGINAL SIGNED BY JERRY SEXTON

CONDITIONS OF APPROVAL, IF ANY: