

OIL CONSERVATION DIVISION
P. O. BOX 7085
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 12-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fed ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO LIFT OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
The Long Trusts

Address of Operator
P.O.Box 1336 Kilgore, Texas 75662

Location of Well

UNIT LETTER F 1980' FEET FROM THE North LINE AND 1980 FEET FROM

THE West LINE, SECTION 11 TOWNSHIP 6S RANGE 35E N.M.P.M.

15. Elevation (Show whether DF, RF, GR, etc.)
4205' G.R.

7. Unit Agreement Name

8. Farm or Lease Name
Hammonds

9. Well No.
1

10. Field and Pool, or Wildcat
Wildcat

12. County
Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

REFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
LL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/15/87 RU Western and spot 6 cement plugs as follows:

plug 1	7649' (T.D.)	40sx	C1 "C"
plug 2	6763'	40sx	C1 "C"
plug 3	4449'	70sx	C1 "C"
plug 4	3238'	55sx	C1 "C"
plug 5	2050'	40sx	C1 "C"
plug 6	SURFACE	10sx	C1 "C"

2/16/87 Nipple down & jet pits. Release rig

Very hole marker has "Big prospect" instead of Hammonds #1

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

PA Comp posted 12-87 E

WED William M. "Dub" Stosh TITLE Operations Engineer DATE 10/15/87

Jack Bissin

OIL & GAS INSPECTOR

DEC 1 1987