

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator MARSHALL PIPE & SUPPLY COMPANY	8. Farm or Lease Name POWELL
3. Address of Operator 13423 Forestway Drive, Dallas, Texas 75240	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>23</u> TOWNSHIP <u>T2S</u> RANGE <u>R29E</u> NMPM.	10. Field and Pool, or Wildcat Tule-Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4372' GL	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

Drilled out below 8-5/8" Casing February 11th, 1989, 1:45 P.M. with 7-7/8" hole.
Drilled TOTAL DEPTH 7-7/8" hole at 7300' on February 27th, 1989.
Ran 211 Jts., 7304' 5-1/2" 17# LT&C R2 and R3 Seamless Casing and set at 7299'. Cemented with 250 sacks Class H Cement, 5# salt per sack, 2% CFR3 with 500 gal mud flush. Ran 17 Centralizers and 17 scratchers. Plug down 5:15 P.M. March 1st, 1989. Pressure up on plug to 1800# and hold for 30 minutes on HOWC chart. Ran float shoe and float collar and latch down plug. Float shoe @ 7299', float collar @ 7270', plug at 7240'.

WAITING ON CEMENT

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. W. Marshall</u>	TITLE <u>Operator</u>	DATE <u>3-2-89</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE <u>MAR 7 1989</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAR 6 1989

OCD
HOBBS OFFICE

2601 11 11