

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

RECEIVED

4. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-9765

SUNDRY NOTICES AND REPORTS ON WELLS

FEB 6 '80

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH OR TO ABANDON A WELL. (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
Name of Operator	8. Farm or Lease Name
TEXACO Inc.	NM 'AS' St. NCT-1
Address of Operator	9. Well No.
P. O. Box 728, Hobbs, New Mexico 88240	1
Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER A 660 FEET FROM THE East 660 FEET FROM	Tulk (Wolfcamp)
THE North LINE, SECTION 6 TOWNSHIP 15-S RANGE 32-E	
11. Elevation (Show whether DF, RT, GR, etc.)	12. County
4325' (DF)	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pull rods, pump & tbq.
2. Clean out well.
3. Set pkr @ 9514'. Acidize perfs. 9700' - 9726' w/6000 gals. 20% HCL Acid containing 30% by volume liquid CO₂. Flushed w/42 Bbls 2% KCL Water containing 30% by volume liquid CO₂.
4. Install pumping equipment.
5. Test & place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Les Clements TITLE Asst. Dist. Supt. DATE 2-4-80
Orig. Signed by
Les Clements
APPROVED BY Oil & Gas Insp. TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

FEB 7 1980