

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

SEP 11 12 03 PM '69

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>E-5667</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>State "B"</b>
9. Well No. <b>2</b>
10. Field and Pool, or Wildcat <b>Anderson Ranch Wolf., No.</b>
12. County <b>Lea</b>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator <b>Union Oil Company of California</b>
3. Address of Operator <b>P.O. Box 671, Midland, Texas 79701</b>
4. Location of Well UNIT LETTER <b>A</b> , <b>990</b> FEET FROM THE <b>North</b> LINE AND <b>990</b> FEET FROM THE <b>East</b> LINE, SECTION <b>33</b> TOWNSHIP <b>15-S</b> RANGE <b>32-E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>4292' GR</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-22-69 Set C.I. bridge plug at 9850'. Dumped 2 sx cement on plug 9850-9828'.

9-2-69 Shot casing at 7690'. Pulled 7697' of 4 1/2", 11.6 & 9.5# N-80 & J-55 casing.

9-4-69 Set cement plugs as follows using 9.3# mud: 40 sacks - 7763 - 7590'  
35 sacks - 5695 - 5590'  
50 sacks - 4161 - 4018'

9-6-69 Shot casing at 1200' & 1000'. Pulled 221' of 8-5/8", 24#, J-55 casing.

Set cement plugs as follows using 9.3# mud: 35 sacks - 1030 - 931'  
50 sacks - 250 - 180'  
15 sacks - 20' - surface

Cut off well head and installed abandonment marker. Well P & A 9-6-69.

Casing left in hole: 11-3/4" - 594'  
8-5/8" - 3884'  
4-1/2" - 2322'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R.G. Ladd, Jr. TITLE District Drilling Supt.

DATE Sept. 9, 1969

APPROVED BY John W. Runyan TITLE Geologist

DATE MAY 6 1971

CONDITIONS OF APPROVAL, IF ANY: