

Attachment to C-103, Unsuccessful Plug Back, dated 12/15/98

10-13-98 RU and swab. Recovered 40 BLW. Fluid to 9200'. Made swab run FL @ 2200'. Made 2<sup>nd</sup> swab run. Released PPI tool and POOH w/ tbg and tools. PU RTTS and TIH w/ 311 jts tbg. RU kill truck and reverse circ hole w/ 200 bbls of lease brine. Set RTTS @ 9711'.

10-14-98 RU and begin swabbing. IFL 200'. Recovered 56 BLW. Swabbing from SN. No shows of oil or gas. 0 load to recover.

10-15-98 RU and swab. No fluid entry. Recovered no fluid. Released pkr. RIH w/ 2 jts tbg and set pkr @ 9773'. RU and swabbed. IFL 1600'. Swab FL down to 9300'. Recovered 42 bbls. RU and Acidize perms from 9802-9817' w/ 2500 gals 15% Ferchek. Hole loaded w/ 2377 gals pumped. RU swab. Recovered 72 BLW – 44 BLTR.

10-16-98 RU and swab. Recovered 2 BO on 1<sup>st</sup> run and trace of oil on 2<sup>nd</sup> run. No shows the remainder of day. Recovered total of 201 bbls. 155 bbls over load.

10-17-98 RU and swab. Recovered trace of oil on 1<sup>st</sup> run. No shows rest of day. Recovered a total of 96 BLW.

10-19-98 RU and swabbed. Made two runs w/ trace of oil on 1<sup>st</sup> run. 100% water on 2<sup>nd</sup> run. Recovered 8 bbls. RIH w/ rods. POH & laid down rods. Released pkr and POH laying down tbg.

10-20-98 Finish laying down 2-7/8" tbg and pkr. ND BOP. NU Wellhead. SWI.  
**Pending P&A.**