

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
E-3510

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER: Salt Water Disposal
2. Name of Operator
Gulf Oil Corp.
3. Address of Operator
P. O. Box 670, Hobbs, NM 88240
4. Location of Well
UNIT LETTER N 3300 FEET FROM THE South LINE AND 1980 FEET FROM
THE West LINE, SECTION 2 TOWNSHIP 16S RANGE 32E N.M.P.M.
7. Unit Agreement Name
8. Farm or Lease Name
Lea CR State (WCT-A)
9. Well No.
3
10. Field and Pool, or Wildcat
11. Elevation (Show whether DF, RT, GR, etc.)
4295' GL
12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set cmt ret @ 1990', test slug 5000 psi. Pump 2290 sl Cl "C"
reat. Displace cmt w/ FW. Spot 100' plugs 1450'-1350' (26 sl),
676'-576' (26 sl) + 100' - surf (26 sl). Weld on dry hole marker.
Clear + Clear loc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED RDP Pate TITLE AREA ENGINEER DATE 9-28-84

ORIGINAL SIGNATURE OF DEPT. SECRETARY

OCT - 4 1984

APPROVED BY DEPT. SECRETARY TITLE DEPT. SECRETARY DATE

CONDITIONS OF APPROVAL, IF ANY: