NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION	CONTRACTOR OF C.C.	Supersedes Old C-102 and C-103
SANTA FE NEW ME	EXICO OIL CONTERDATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.	PR-4DEC 29 11 47 PN '66	5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		E-5301
SUNDRY NOTICES AND (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR T USE "APPLICATION FOR PERMIT -" (F	OREPORTS ON WELLS TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ORM C-101) FOR SUCH PROPOSALS.)	
1. OIL GAS X OTHER-	Formerly produced oil)	7. Unit Agreement Name
WELL WELL OTHER-	8. Farm or Lease Name	
Sunray DX 011 Company		
		State Land "76" 9. Well No.
3. Address of Operator		
P. O. Box 1416, Roswell, New M	1	
4. Location of Well	0 th 1090	10. Field and Pool, or Wildcat
UNIT LETTER J 4620 FEET FROM	M THE LINE AND FEET F	ROM Undesignated
THE East LINE, SECTION T	rownship 168 Range 32E	ирм. ())))))))))))))))))))))))))))))))))))
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
	4319 DF	
^{16.} Check Appropriate Box	To Indicate Nature of Notice, Report or	Other Data
NOTICE OF INTENTION TO:	_	ENT REPORT OF:
PERFORM REMEDIAL WORK	G AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	NGE PLANS CASING TEST AND CEMENT JOB	
—	OTHER Recomplete wel	1 in Morrow-gas X
OTHER		uced from Devonian-oil)

: ~

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1. Pulled reds pump. Displaced hole w/fresh water.
- 2. Pumped into Devonian perfs 13,352-92. Mixed 200 sxs incor poznix and squeezed Devonian perfs to 3000%. P.B. w/cement to 12,510'.
- 3. Perf 4 holes 12,188-89 for lower block squeeze of Morrow. Squeezed perfs to 6900# w/48 sxs incor posmix.
- 4. Perf 4 holes 12,141-42 for upper block squaeze of Morrow. Squeezed perfs to 5000# w/50 sxs. Communication existed around packer. Found hole in casing at 6835. Set packer at 6625 and squeezed hole at 6835 w/100 sxs incor posmix to 2000#.
- 5. Drilled cast and cleaned out to 12,175'. Tested csg. to 1500# for 30 min. Held OK.
- Perf with 1/2" bullets, one hole at each of the following depths 12,160', 12,161', 12,163', 12,165', 12,166', 12,167', 12,169', 12,170'. Well kicked off after perforating.
- 7. Ran Baker Model "D" pkr and set @ 12,150'. Tested at rate of 6400 MCFPD for 2 hrs. SI overnight and well blew out of 9 5/8" intermediate csg. Picked up tbg out of Model "D" packer. Killed well w/salt water. Laid 50 sx cmt plug from 12,140 up.

(OVER)

- 8. Located hele in 5 1/2" esg at 6735'. Displaced 900 sxs incor pormix out hele. Had good circulation out of 9 5/8" during job. Squeezed hele w/70 sxs to 3000#. WOC 12 hrs.
- 9. Top of cement by survey behind 5 1/2" @ 3430'. Base of 9 5/8" csg. @ 4203'.

18. I hereby certify that the information above is true and comple	te to the bes	t of my knowledge and belief.		
SIGNED BE T. Brewley	TITLE	District Engineer	DATE_	December 28, 1966
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	T IT LE		DATE _	- • <u>^</u>

- 10. Drilled cmt to 6750'. Prejeuted cas to 2000f for 30 min. Held OK. 11. Drilled cmt and cleaned out to 12,050'. Pressured tested cas. to 2000f for 30 min. Held OK.
- 12. Perf. 4 holes 12,039-40 for squeeze to insure isolation of Morrow zone. Squeezed perfs in 3 stages (100 sxs each stage) to 8500#. Reserved 20 sxs. WOC 10 hrs.
- 13. Drilled out cmt and Model "D" pkr and cleaned out to 12,180. Did not find cament below packer indicating communication was upward only. 14. Set Baker Model "D" prod. pkr at 11,975. Ran tbg, set in pkr. Swabbed and well kicked
- off. Acidized Morrow w/1000 gal BDA. Swabbed and well kicked off flowing to atmosphere rate of 6,000 MCFPD. Shut in well until market connection is made. Monitored annulus pressure for one week and did not note any communication indication.