Form C-103 (Revised 3-55) KICO OIL CONSERVATION COMMISSION CELLANEOUS REPORTS ON WELLS o appropriate District Office as per Commission Rule 1186) 23 Continental Oil Company, Box 427, Hobbs, New Mexico COMPANY (Address) LEASE Williams Ranch Unit WELL NO. UNIT L S 26 1 6-29-55 DATE WORK PERFORMED POQL Undesignated This is a Report of: (Check appropriate block) Results of Test of Casing Shut-off Beginning Drilling Operations Remedial Work Plugging Other Detailed account of work done, nature and quantity of materials used and results obtained. The subject wall was plugged and abandoned as a dry hole, The following plugs were sets 13,700-13,754 with 20 sacks coment. 12,538-12,638' with 40 sacks cement. 10,055-10,1554 with 40 sacks cement. .206-4.329 with 50 sacks coment. A 4" marker was set at top of surface casing with 10 sacks and location restored to original condition. 9 5/8" cosing was shot off at approximately 1925" and 61 joints were recovered. Well was neither shot nor acidized. Casing was not perforated. Plugging started 6-24-55. Plugging completed 6-29-55. FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY Original Well Data: DF Elev. 4313 TD 13,754 PBD Prod. Int. Compl Date 6-2 Tbng, Dia Thng Depth Oil String Dia Oil String Depth Perf Interval (s) Producing Formation (s) Open Hole Interval RESULTS OF WORKOVER BEFORE AFTER Date of Test Oil Production, bbls. per day Gas Production, Mcf per day Water Production, bbls. per day Gas-Oil Ratio, cu. ft. per bbl. Gas Well Potential, Mcf per day Witnessed by (Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Oil & Gas Inspector

Name

Position

Metrict Superintendent

Date

Title

Continental Oil Commany Company

doublinested the Cornery Con 127, Hobbs, Ber Herdee

abditional amount in

7 A

INE

E 25 - 5 5

74!

₹₹-₹\$₩Ò ingloot-mated

The subject woll can plugged and abandoned as a day hole. the rollo dury plugo more solls

18,700-13,756 with 20 cacies commin. 12,538-12,638 with 40 scoils commt.

10,055-10,155° tdth 40 secte carmte

6.206-4.329 with 50 early conent.

A has nurseen was son at top of surface casting with Mi masks and localition restored to orderinal condition. 9 5/8" caring was shot off at approximately 1925; and 61 joints were

coll una actioner give non residence. Castny una not perforated.

American started belless.

Plugging concloted 6-79-55.

Maintet Superintendent Cartif ortal Oli Cerany