STATE OF NEW MEXICO ENLAGY AND MINERALS DEPARTMENT

MO. OF COMISS MILITINGS	
DISTINBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

Form C-103 Revised 10-1-78

SANTA FE, NEW MEXICO 87501	Kevised 10-1-70
FILE	5a. Indicate Type of Lease
U.S.G.S.	State Foe XX
OPERATOR	5. State Oil & Gas Lease No.
SUNDAN MOTICES WAS DEBODES ON MELLS	
SUNDRY NOTICES AND REPORTS ON WELLS THE FORM FOR PROPOSALS TO DILL, OF TO OFF PEN OF PLUG BACK TO A DIFFERENT RESERVOIR.	
1.	7. Unit Agreement Name
WELL OTHER. X - Water Injection Well	
2. Name of Operator	8, Farm or Lease Name
Anadarko Petroleum Corporation	Taylor
3. Address of Operato:	9. Well No.
P. O. Drawer 130, Artesia, New Mexico 88210	2
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER M 990 FEET FROM THE South LINE AND 330 FEET FROM	Grayburg-Jackson-SR-Q-SA
V 20 16C 22F	
THE West LINE, SECTION 30 TOWNSHIP 16S RANGE 32E NAMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
Unknown	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Otl	
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
	_
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLAYS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
PULL OR ALTER CASING CHANGE PLAYS CASING TEST AND CEMENT JQB OTHER Recover packet	c & Clean out XX
OTHER	<u>a dreum out</u>
VINES	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.	
Note: When well was pulled earlier, could not pull packer. Shot off paper hole.	acker and it fell into
1. Rigged up pulling unit; tripped out of hole with tubing.	
2. Ran overshot and jars; could not recover packer; pushed packer to be	ottom of hole@4015';
TOH.	
3. Ran injection packer on 2-3/8' plastic lined tubing.	
4. Set packer and tested casing to 500#; would not hold; TOH.	annal man
5. WIH with packer and RBP; tested casing and found holes in casing @	2800°; TOH.
6. Ran tubing in well open-ended.7. Rigged down pulling unit; left well shut in.	
7. Rigged down pairing date, felt well sade in.	
Note: Plan to return to this well later and repair.	
	•
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Field Foreman	DATE February 6, 1986
CHARACTER SACTURES BY CHARACTER OF WARRE	EED 1 6 1000
APPROVED BY DISTRICT TO THE TITLE	FEB 1 0 1986