

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☐	Fee ☐
5. State Oil & Gas Lease No. W-7177	
7. Unit Agreement Name Robinson Unit	
8. Farm or Lease Name Robinson Unit Tr. 5-31	
9. Well No. 10	
10. Field and Pool, or Wildcat Malj. Grayb. S.A.	
12. County Lee	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DREDGE OR PLUG BACK TO A DIFFERENT RESERVOIR.
(IS APPLICABLE ON FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.)

1. Name of Operator I. B. Box 837, Hobbs, New Mexico 34240	2. Location of Well UNIT LETTER J, 1880 FEET FROM THE South LINE AND 1980 FEET FROM THE 1-30 LINE, SECTION 32, TOWNSHIP 16, RANGE 32, N.M.P.M.
3. Elevation (Show whether DF, RT, GR, etc.) 4106 GR	4. Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug and abandon in the following manner: No csg. will be pulled.

1. Set 100' cement plug above perforations 3805-3869' (Overall)
2. Fill casing with mud.
3. Set 100' cement plug at 976' (Top Salt)
4. Set 10' plug at surface with marker
5. Clear, level and clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Rashid B. Dora TITLE District Superintendent DATE 10/7/74

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: