NO. OF COPIES RECEIVED			Form C-103	
DISTRIBUTION	ISTRIBUTION		Supersedes Old	
SANTA FE	A FE NEW MEXICO OIL CONSERVATION COMMISSION		C-102 and C-103	
FILE			Effective 1-1-65	
U.S.G.S.			5a. Indicate Type of Lease	
LAND OFFICE			State 🗙 Fee	
OPERATOR			5. State Oil & Gas Lease No.	
			B-7180-2	
(DO NOT USE THIS FORM FOR PU USE "AP PLICA				
1. OIL GAS WELL .	OTHER-		7. Unit Agreement Name	
2. Name of Operator	8. Farm or Lease Name			
AZTEC OIL & GAS COMP.	Hudson - State			
	9. Well No.			
<b>P. O. Box 837, HOJ3BS</b> 4. Location of Well	1			
	10. Field and Pool, or Wildcat			
UNIT LETTER L	Undesignated			
THE West LineNE, SECT				
	12. County			
	Lea			
Check	Appropriate Box To Indicate Na	ture of Notice, Report or O	ther Data	
			T REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JQB		
OTHER		OTHER		
17. Describe Proposed or Completed	perations (Clearly state all pertinent durai			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug and abandon in the following manner:

- 1. Load hole with mud laden fluids.
- 2. Set 100' plug from 3260 3160' (Perfs at 3232-54').
- 3. Cut off  $4\frac{1}{2}$ " casing at 2700'. Set 100' plug in top of casing stub.
- 4. Set 100' plug at top Salt at 2000'
- 5. Set 100' plug at Base Surface casing at 330'.
- 6. Set 10 sx. plug in top surface casing. Place proper marker, clear and level location.

18. I hereby	certify that the information a	bove is true and comple	ete to the best of my knowledge and belief.		
SIGNED	orginial signed by: LESTER L DUKE		TITLE District Superintendent	DATE	June 26, 1972
APPROVED BY	Y NS OF APPROVAL, IF ANY:	Orig. Signed by Joe D. Ramey Dist. I, Supv.	TITLE	DATE _	JUN 28 1972

RECEIVED

.

JUN 27 1972

OIL CONSERVATION COMM. HOBUS, N. H.