

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office Las Cruces

Lease No. 000576

Unit P

RECEIVED

SEP 13 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	
WATER INJECTION WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

JUNE 1, 1963

19

Well No. 1148 is located 060 ft. from N line and 060 ft. from E line of sec. 3

SE 1/4. SE 1/4. 3 17 32 P
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)


MALJAMAR LEA NEW MEXICO
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

CLEANED THIS WELL OUT HAD LEAK IN CASIN AT 3830 FT. RUN 2460 FT. 2 3/4" TUBING WITH PACKER STARTED INJECTION WATER THROUGH TUBING DEC. 5. 1961 FRAZER CAME IN JANUARY 1962. FROZE AND BURSTED THE LINES, STARTED INJECTIO THE SECOND TIME IN MARCH 1962.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company LEONARD NICHOLS

Address MALJAMAR,

NEW MEXICO

By

O.P. McCutcheon

Title SUPT.