

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

M 0915712

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Iles Federal Report 2

9. WELL NO.

15

10. FIELD AND POOL, OR WILDCAT

Grayburg San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 4; 17-32

12. COUNTY OR PARISH 13. STATE

Iles New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ **AUG 17 11 26 AM '63**
2. **Standard Oil Company of Texas**
A Division of Chevron Oil Company
3. ADDRESS OF OPERATOR
3610 Avenue S - Snyder, Texas
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
**Unit 1; 990' FWL and 1980' FWL of Section 4,
T-17S, R-32E**
14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4005 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) **Supplementary Well History**
(NOTE: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Move in pulling unit, pulled packer and tubing.
2. Cleaned out to 3980 with sand pump.
3. Located casing leak between 317' and 175', backed off casing with string shot at 342', pulled 11 joints 5 1/2" casing. Ran 11 joints new 5 1/2" 17 1/2 J-55 STAC casing, displaced hole with Hydrastim mud. Screwed on to casing, nipped up wellhead, tested casing with 2500 psi, no pressure loss in 30 minutes.
4. Set retrievable bridge plug at 3996', perf interval 3832'-3836', 3876'-3880' with 4 GRT.
5. Acidized 3832-3888 with 1500 gals mud acid with Polymer.
6. Ran tubing and packer, set packer at 3940', nipped up wellhead, placed on injection.

18. I hereby certify that the foregoing is true and correct

SIGNED

E. W. Milants
E. W. Milants

TITLE

District Engineer

DATE

August 10, 1963

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

AUG 13 1965

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1983-O-849229

507-551