

UNIT STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions
verse side)

Modified Form No.

MX60-3160-4

5. LEASE DESIGNATION AND SERIAL NO.

LC-029406(B)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

MAY 7 8 31 AM '90

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER WIW

2. NAME OF OPERATOR
Marbob Energy Corporation

3a. Area Code & Phone No.
(505) 748-3303

8. FARM OR LEASE NAME

Grace Mitchell "B"

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Maljamar Grbg SA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 5-T17S-R32E

3. ADDRESS OF OPERATOR
P. O. Drawer 217, Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980 FNL 660 FEL

Unit A

14. PERMIT NO.

30-025-00470

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4131' DF

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Return to active injection ☒

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

4/4/90 RU, RIH w/overshot, retrieved Baker Lockset plug, RIH w/ 3 3/4" bit and 4 1/2" csg scrapper, CO to 3810'.

4/5/90 Circ hole clean, POH w/bit and scrapper, RIH w/pkr & plug to find hole in csg, set plug @ 3180', tstd csg from 1750-3180' to 2100#--held okay, tstd csg from 1750' to surface to 800#--held okay, POH w/pkr & plug, RIH w/3 3/4" bit and CO to PBTD, POH.

4/6/90 RIH w/115 jts. new 2 3/8" plastic coated tbq, circ pkr fluid, set pkr @ 3819', tstd csg to 300# for 15 minutes--held okay, pmpd 400 gals 20% NE ac and flush w/24 bbls. wtr.

Robert Chase obtained verbal approval to proceed with the work from Jerry Sexton 4/4/90.

ACCEPTED FOR WORK

Ad

CARISBAD, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Clerk

DATE 5/3/90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

MAY 7 8 30 AM '50

CANAL
ADL...

FILE
15

