

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| |
|---|
| WELL API NO. |
| 30-025-00497 |
| 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No. |

| | |
|---|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Lease Name or Unit Agreement Name Maljamar Grayburg Unit |
| 2. Name of Operator Chevron U.S.A. Inc. | 8. Well No. 53 |
| 3. Address of Operator P.O. Box 670, Hobbs, NM 88240 | 9. Pool name or Wildcat Maljamar (Grayburg/SA) |
| 4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>610</u> Feet From The <u>West</u> Line Section <u>10</u> Township <u>17S</u> Range <u>32E</u> NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4128</u> | |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: TA ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed: 4-5-89

MIRU. POH w/production tbq. Make bit and scraper run. Set WL CIBP at 3805'.
Tst csg to 500psi for 30 min, ok. RIH w/production tbq. Circulate wellbore
w/inh pkr fl. NDBOP NUWH. Change status to TA'd.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. K. Elmore TITLE Technical Asst. DATE 4-7-89
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

APR 11 1989

APR 10 1988
OCD
HOBBS OFFICE

4-5

829

MTU #53 CS6 Test

7

RECEIVED

APR 10 1989

GOD

HOBBS OFFICE