

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THE STATE OF
NEW MEXICO

Permit No. 42-11424
LOCAL DESIGNATION AND SERIAL NO.

LC 059576

6. INDIAN, ALIEN, OR TRUST LAND

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ 2. NAME OF OPERATOR Chevron Oil Company 3. ADDRESS OF OPERATOR P. O. Box 1660, Midland, Texas 79701 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also notice 17 below.) At surface Unit A, 660' FNL, 660' FEL, Section 10, T-17-S, R-32-E, NMMP 14. PERMIT NO.	7. UNIT AGREEMENT NAME Maljamar (Grayburg) 8. FARM OR LEASE NAME Maljamar Unit 9. WELL NO. 49 10. FIELD AND POOL, OR WILDCAT Maljamar Grayburg-San Andres 11. SEC., T., R., M., OR BLM, AND SURVEY OR AREA Sec. 10, T-17-S, R-32-E NMMP 12. COUNTY OR PARISH Lea 13. STATE New Mexico
15. ELEVATIONS (Show whether DF, ET, GR, etc.) GR 4282'	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

PRELIMINARY INTENTION TO: <table border="0"> <tr> <td>TEST WATER SHUT-OFF</td> <td>WELL OR ALTER CASING</td> </tr> <tr> <td>FRAC TURE TREAT</td> <td>MULTIPLE COMPLETE</td> </tr> <tr> <td>SHOOT OR ACIDIZE</td> <td>ABANDON*</td> </tr> <tr> <td>REPAIR WELL</td> <td>CHANGE PLANS</td> </tr> <tr> <td>(Other)</td> <td>XX</td> </tr> </table>		TEST WATER SHUT-OFF	WELL OR ALTER CASING	FRAC TURE TREAT	MULTIPLE COMPLETE	SHOOT OR ACIDIZE	ABANDON*	REPAIR WELL	CHANGE PLANS	(Other)	XX	SUBSEQUENT REPORT OF: <table border="0"> <tr> <td>WATER SHUT-OFF</td> <td>REPAIRING WELL</td> </tr> <tr> <td>FRAC TURE TREATMENT</td> <td>ALTERING CASING</td> </tr> <tr> <td>SHOOTING OR ACIDIZING</td> <td>ABANDONMENT*</td> </tr> <tr> <td>(Other)</td> <td></td> </tr> </table>		WATER SHUT-OFF	REPAIRING WELL	FRAC TURE TREATMENT	ALTERING CASING	SHOOTING OR ACIDIZING	ABANDONMENT*	(Other)	
TEST WATER SHUT-OFF	WELL OR ALTER CASING																				
FRAC TURE TREAT	MULTIPLE COMPLETE																				
SHOOT OR ACIDIZE	ABANDON*																				
REPAIR WELL	CHANGE PLANS																				
(Other)	XX																				
WATER SHUT-OFF	REPAIRING WELL																				
FRAC TURE TREATMENT	ALTERING CASING																				
SHOOTING OR ACIDIZING	ABANDONMENT*																				
(Other)																					

17. DESCRIBE IN DETAIL THE WORK DONE ON THIS WELL. CLEARLY STATE ALL PERTINENT DETAILS, AND GIVE PERTINENT DATES, INCLUDING ESTIMATED DATE OF STARTING ANY FURTHER WORK. IF WELL IS BEING FULLY DRILLED, GIVE SUBSURFACE LOCATIONS AND MEASURED AND TRUE VERTICAL DEPTHS FOR ALL MARKERS AND LOGS PERTINENT TO THE WORK.

Filed in accordance with the New Mexico Oil Conservation Commission letter dated September 13, 1974, regarding notification of status of inactive wells.

The temporary abandonment of this well commenced on April 1, 1967. Present plans call for this well to be plugged and abandoned by November 1, 1976.

NOV 1 1976

18. I hereby certify that the foregoing is true and correct

SIGNED W. A. Gougeau TITLE Area Supervisor DATE Oct. 17, 1975
(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
COMMISSIONS OF APPROVAL, IF ANY:

APPROVED

OCT 23 1975
JIM SIMS
ACTING DISTRICT ENGINEER