



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office
Lease No. LC 064150
Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	Report of Whipstock to Sidetrack
	Junk in indeterminate Direction

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

North Maljamar Deep Unit No. 1 September 17, 1962

Well No. 1 is located 660 ft. from ~~N~~_S line and 1930 ft. from ~~E~~_W line of sec. 10

SE/4-SW/4 Sec. 10 T-17-S R-32-E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4123 ft. RDB

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 9/12/62 29 Drill Collars were dropped in 12-1/4" Hole T.D. 4119. Subsequent fishing operations recovered 22 collars, leaving 7 collars in hole. Unable to get fish with overshot, ran mill to dress off top of collars. Milled off 3 Ft. of fish. Still unable to recover fish. Lost overshot in hole. Set 125 Sx cmt plug in hole containing 10% sand and 2% calcium chloride tagged top cmt 3711. Dressed off to 3752 and set whipstock. Now drilling in an undetermined direction to complete 12-1/4" hole for intermediate casing.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum Corporation

Address Box 68

Hobbs, New Mexico

By

Original signed by:
V. E. SLATTERY

Title Area Superintendent