NO. OF COPIES RECE	IVED		•			Form C-103	
DISTRIBUTION						Supersedes Old	2
SANTA FE		NEW	MEXICO OIL CONS	ERVATION COMMISSION		C-102 and C-103 Effective 1-1-65	
FILE				:			
U.S.G.S.						5a. Indicate Type o	f Lease
LAND OFFICE						State X	Fee 📋
OPERATOR						5. State Off & Gas	
						<u> State - 3-</u>	-871
(00 NOT USE	SUNDR'		ND REPORTS ON OR TO DEEPEN OR PLUG B. (FORM C-101) FOR SUC	WELLS ACK TO A DIFFERENT RESERVO H PROPOSALS.)			
i.	GAS					 Unit Agreement : IJONE 	Name
2. Name of Operator	WELL L	OTHER-				8. Farm or Lease N	dame NCT-3
						Jew Mexico '	
TEXACO				<u>, </u>		9. Well No.	<u> </u>
3. Address of Operato		Hobbs. New	Mexico 88240			21	<u> </u>
4. Location of Well	2011 1209	.10 , 1,				13. Field and Pool	, or Wildcat
	g 1	.980	FROM THE East	1980	_ FEET FROM _	Maljamar	
UNIT LETTER		PEEL 1	FROM THE	LINE AND			
THE Morth	LINE, SECTIO	12	TOWNSHIP 17-S	RANGE 32-E	NMPM.		
				DE DE CD		12. County	HHHH
		11111	levation (Show whether 238' (GL)	DF, KI, GK, etc.)		Lea	
16.				CM D.		na Data	******
				lature of Notice, Rep		REPORT OF:	
	NOTICE OF IN	NIENTION IC); 	302	JEQUEN !	KEI OKI OI	
			٢1		r to the second		C CASING
SESSORIUS DELLEDIAL M	VOR V		PLUG AND ABANDON	REMEDIAL WORK	1 4-	ALTERIN	10 0 20 1140
PERFORM REMEDIAL W	=		PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING OPNS.			D ABANDONMENT
TEMPORAR;LY ABANDO	м			REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J	QB		=======================================
	м		PLUG AND ABANDON	COMMENCE DRILLING OPNS.	де П		=======================================
TEMPORARILY ABANDO	м			COMMENCE DRILLING OPNS.	IQB		=======================================
TEMPORAR(LY ABANDO PULL OR ALTER CASIN	on G		CHANGE PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER		PĽUG AN	D ABANDONMENT
TEMPORAR(LY ABANDO PULL OR ALTER CASIN	ed or Completed Op		CHANGE PLANS	COMMENCE DRILLING OPNS.		PĽUG AN	D ABANDONMENT
OTHER 17. Describe Proposition's SEE RUL	ed or Completed Op	perations (Clearly	change plans	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER ails, and give pertinent date		PĽUG AN	D ABANDONMENT
OTHER 17. Describe Proposition's SEE RUL	ed or Completed Op	perations (Clearly	CHANGE PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER ails, and give pertinent date		PĽUG AN	D ABANDONMENT
other 17. Describe Proposition of See Rule The follow	ed or Completed Or E'1103.	perations (Clearly	change plans	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER ails, and give pertinent date		PĽUG AN	D ABANDONMENT
other 17. Describe Proposition of See Rule The follow	ed or Completed Op	perations (Clearly	change plans	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER ails, and give pertinent date		PĽUG AN	D ABANDONMENT
TEMPORARILY ABANDO PULL OR ALTER CASIN OTHER 17. Describe Proposition (No. 1) Pulled	ed or Completed Or E 1 103. Ving work ha	perations (Clearly as been com	y state all pertinent det	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT J OTHER ails, and give pertinent date	es, including e	PLUG AN	arting any proposed
The follow 1) Pulled 2) Tagged 4312'	ed or Completed Or E 1 103. Ving work ha	erations (Clearly as been com oump. tog, strap	y state all pertinent det	commence drilling opns. casing test and cement in other other ails, and give pertinent date ject Well:	es, including e	PLUG AN	arting any proposed
TEMPORARILY ABANDO PULL OR ALTER CASIN OTHER 17. Describe Proposition follow The follow 1) Pulled 2) Tagged 4312'. 3) Set RT	ed or Completed Or E 1 103. Ving work ha A rods and p A bottom w/t	perations (Clearly as been compump. Jog, strap 4098'.	y state all pertinent det appleted on sub,	commence drilling opns. casing test and cement in other other ails, and give pertinent date ject Well:	ill © 434	Piug An extimuted date of st 21', btm. pe	arting any proposed
The follow 1) Pulled 2) Tagged 4312' 3) Set RI 4) Frac p	ed or Completed Or grinos. Ving work has i rods and production w/t. CTS packer @ perfs 4146	perations (Clearly as been com oump. log, strap 4098'. -4312' wages.	y state all pertinent det appleted on sub; tubing out of	commence drilling opns. casing test and cement in other	ill © 434	extimuted date of st 21', btm. pe	arting any proposed
The follow 1) Pulled 2) Tagged 4312'. 3) Set RT 4) Frac p 24 BS 5) Recove	ed or Completed Or E 1103. Ving work has and prods and prods and prods and prods and prods packer @ Oerfs 4146' Completed Or E 1103.	perations (Clearly as been compump. Dog, strap 4098'. 4312' wages. run rods &	v state all pertinent det upleted on sub; tubing out of v/30,000 gals a pump.	commence drilling opns. casing test and cement in other	ill © 43%	extimated date of st	erting any proposed

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE Asst. Dist. Superintendent

DATE

DATE

CONDITIONS OF APPROVAL, IF ANY: