

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-00525

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Southwest Royalties, Inc.

3. Address of Operator
P.O. Box 11390, Midland, TX 79702

7. Lease Name or Unit Agreement Name
New Mexico "O" State

8. Well No. 23

9. Pool name or Wildcat
Maljamar

4. Well Location
Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line
Section 12 Township 17-S Range 32-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4248' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/11/02 Rig up plugging unit.
2/13/02 Mud up hole, spot 50 sx cmt. @ 4230', WOC & tag @ 3699', spot 25 sx @ 3550'.
2/14/02 Perf @ 2400', sqz 50 sx cmt., WOC & tag @ 2260', perf 4 holes @ 1200', sqz. 50 sx.
2/15/02 Tag cmt. plug @ 1065', perf 4 holes @ 325', sqz. 50 sx WOC. RIH to tag plug,
(did not tag) re-sqz 50 sx WOC.
2/18/02 RIH & tag plug @ 185', spot 10 sx to surface. Rig down & MOL.
Cut off wellhead, install dry hole marker. Clean location.

Gary W. Wink

GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Roger Massey* TITLE Agent DATE 2/27/02
TYPE OR PRINT NAME Roger Massey TELEPHONE NO. (915) 530-0907

(This space for State Use)

JAN 17 2003

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

2/1/02