

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
SEE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Unit Agreement Name
3. Name of Operator MONUMENT ENERGY CORPORATION	8. Farm or Lease Name N.M. "O" STATE NCT-3
4. Address of Operator P.O. BOX 966 1476 LOVINGTON, NEW MEXICO 88260	9. Well No. 23
5. Location of Well UNIT LETTER E 660 FEET FROM THE WEST LINE AND 1980 FEET FROM THE NORTH LINE, SECTION 12 TOWNSHIP 17-S RANGE 32-E N.M.P.M.	10. Field and Pool, or Wildcat MALJAMAR GRAYBURG SAN ANDRES
15. Elevation (Show whether DF, RT, GR, etc.) 4255 D. F.	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. PULLED STUCK RODS AND TUBING.
2. CLEAN WELL TO T.D.
3. ACIDIZE WITH 15% NE ACID, 500 GALLONS.
4. SWAB ACID BACK.
5. ACIDIZE WITH 1500 GALLONS 15% NE ACID.
6. SWAB BACK ACID WATER.
7. PUT WELL ON PRODUCTION IN GRAYBURG SAN ANDRES.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE PRESIDENT [Signature] 3-12-79

Orig. Signed by
John Runyan

APPROVED BY [Signature] TITLE P DATE MAR 15 1979

CONDITIONS OF APPROVAL, IF ANY Geologist