

|                        |  |  |
|------------------------|--|--|
| NO. OF COPIES RECEIVED |  |  |
| DISTRIBUTION           |  |  |
| SANTA FE               |  |  |
| FILE                   |  |  |
| U.S.G.S.               |  |  |
| LAND OFFICE            |  |  |
| OPERATOR               |  |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-85

|  |
|--|
| 5a. Indicate Type of Lease<br>State <input type="checkbox"/> Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No.   |
| 7. Unit Agreement Name   |
| 8. Farm or Lease Name<br><u>A.E. Taylor</u>  |
| 9. Well No.<br><u>3</u>  |
| 10. Field and Pool, or Wildcat<br><u>Mallamar 6/5A</u>   |
| 12. County<br><u>Lea</u>   |

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|  |
|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <u>Injection</u>  |
| 2. Name of Operator<br><u>CONOCO INC.</u>  |
| 3. Address of Operator<br><u>P. O. Box 460, Hobbs, N.M. 88240</u>  |
| 4. Location of Well<br>UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM<br>THE <u>West</u> LINE, SECTION <u>14</u> TOWNSHIP <u>17S</u> RANGE <u>32E</u> NMPM. |
| 15. Elevation (Show whether DF, RT, GR, etc.)  |

## 18. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|  |  |  |   |
|--|--|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>               | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                | COMMENCE DRILLING OPNS. <input type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>                       | CASING TEST AND CEMENT JOBS <input type="checkbox"/> |   |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- ① MIRU. Pull tbg & pkr out of hole. If fill is inside csq, clean out to 50' below csq shoe @ 3956'. If fill is below 4006', fill with sand or oyster shells to ± 50' below csq shoe.
- ② Spot 100' cmt plug from 3906' to 4006'.
- ③ Spot 100' cmt plug @ base of the salt (2150'-2250')
- ④ Perf @ 970' w/ 4 JSPE. Set pkr @ 900'. Pump wtr down surf. to attempt circ. to surf. I can't pump-in, spot 1½ bbls 15% HCL.
- ⑤ After establishing pump-in rate, set cmt retainer @ 900' and pump 260s cmt and circ. to surface.
- ⑥ Spot 50' cmt plug @ surface. Cut of csq to restored ground level and install abandonment marker. Rig down.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Administrative Supervisor DATE 7-2-86

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_ DATE JUL 7 1986

NMCO-1466