

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-029405(b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME MCA
2. NAME OF OPERATOR Continental Oil Company		8. FARM OR LEASE NAME MCA Unit
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, NM 88240		9. WELL NO. 7
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650' SNL + 2310' FWL of § Sec. 17		10. FIELD AND POOL, OR WILDCAT Maj. G-SA Ppaw.
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4032' df	11. SEC., TWP., M., OR BLK. AND SURVEY OR AREA Sec. 17, T-17S, R-32E
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Perfs 5 1/2" csg. w/1 JSP3 at 3782', 79', 76', 3773', 3691', 75', 71', 62', 53', 44', 18', 17', 11' and 3607'. Spotted acid over Perfs 3782-3773'. Set Pbe. at 3714 and filled w/750 gals 15% NE Acid. Frac'd w/5000 gals TPW w/10,000 # 20/40 sand. Filled Perfs 3691-3607' w/1500 gals. 15% NE acid. Frac'd w/20,000 gallons TPW w/40,000 # 20/40 sd. Set pbe at 3545' w/12 lbs tension + placed on inj.

Completed-6-19-73

18. I hereby certify that the foregoing is true and correct

SIGNED

M. E. Heakley

TITLE Admin. Supervisor

DATE

7-31-73

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

AUG 6 1973

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side