
Submit 3 Copies
to Appropriate
District Office

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980. Hobbs NM 88240	OIL CONSERVATI 2040 South Pr		WELL API NO. 30-025-12558 00574
DISTRICT II 811 South First, Artesia, NM 88210	Santa Fe, New Me	exico 87505	5: Indicate Type of Lease
<u>DISTRICT III</u> 1000 Rio Brazos Rd, Aztec, NM 8741	0		STATE FEE
			B-2366
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS).			7. Lease Name or Unit Agreement Name
. Type Of Well: OIL S GAS DELLE			Leaker CC-State
WELL WELL L.J.	OTHER		
fack Energy Corporation Address of Operator			8. Well No.
O. Box 960, Artesia, NM 882	11-0060		9. Pool name or Wildest
Well Location	11-0900		Maljamar Grayburg SA
Unit Letter H: 1	1980 Feet From The North	Line and 6	40 Feet From The East Lin
Section 16			NMPM Lea County
	10. Elevation (Show wheth	er DF, RKB, RT, GR, etc.) 4055 GR	
	k Appropriate Box to Indicate	1	_
	NTENTION TO:	SUE	ISEQUENT REPORT OF:
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
MPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	
ULL OR ALTER CASING		CASING TEST AND CE	EMENT JOB I
			-
THER: 12. Describe Proposed or Complete work) SEE RULE 1103.	d Operations (Clearly state all partinent de	OTHER	Put well back on Production
2. Describe Proposed or Complete work SEE RULE 1103.		OTHERalls, and give persinent dates, in	Put well back on Production
2. Describe Proposed or Complete work SEE RULE 1103.		OTHERalls, and give persinent dates, in	Put well back on Production
2. Describe Proposed or Complete work SEE RULE 1103.		OTHERalls, and give persinent dates, in	Put well back on Production
2. Describe Proposed or Complete work) SEE RULE 1103. //01/93 Rig up, Pulled 5 1/2 pkr		OTHER alls, and give persinent dates, interpretation W/ 2 3/8" tbg to 3969', rat	Put well back on Production cluding estimated date of storting any proposed in 3/4 & 5/8 rods. Put well back on production
12. Describe Proposed or Complete work) SEE RULE 1103. 1/01/93 Rig up, Pulled 5 1/2 pkr	r & plastic coated tbg. Ran in hole	other alls, and give pertinent dates, in w/ 2 3/8" tbg to 3969', rat d belief Production	Put well back on Production cluding estimated date of starting any proposed in 3/4 & 5/8 rods. Put well back on production on Clerk DATE 5/18/76
22. Describe Proposed or Complete work) SEE RULE 1103. //01/93 Rig up, Pulled 5 1/2 pkr hereby certify that the information above is its its space for State Use)	crue and complete to the best of try knowledge and Crissa D. C	other alls, and give pertinent dates, in w/ 2 3/8" tbg to 3969', rat d belief Production	Put well back on Production cluding estimated date of starting any proposed in 3/4 & 5/8 rods. Put well back on production



05/