

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Aramis, NM 88210

DISTRICT III
1000 Rio Bonos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-00578
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-155-5
7. Lease Name or Unit Agreement Name	MCA Unit Bty 2
8. Well No.	12
9. Pool name or Wildcat	Maljamar (G-SA)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER ☒ Injection	2. Name of Operator Conoco Inc.
3. Address of Operator 10 Lesta Dr. Midland, TX 79705	4. Well Location Unit Letter N : 330 Feet From The South Line and 2310 Feet From The West Line Section 16 Township 17S Range 32E NMPM Lea
10. Elevation (Show whether D.F., R.E.B., RT, GR., etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER: ☐	CASING TEST AND CEMENT JOB ☐	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-5-91 Run bit & scraper, tag at 3615, pull out, run bit & drill collars, clean well out to 3870, pull out of hole, shut down.
2-6-91 Run cmt ret, set at 3550, pmp 100 sks cmt, sting out of ret, spot 25 sks cmt from 3550 to 3368, circ mud, pull tbg out to 2051.
2-7-91 Spot 25 sks cmt from 2051 to 1951, pull tbg to 1075, spot 17 sks cmt from 1075 to 976, pull tbg out, perf well at 875, pressure up to 1000# - could not pmp into well, spot 17 sks cmt from 925 to 825, perf well at 150, circ 50 sks cmt down 7" csg back up 8 1/2" - SD. Tag cmt at 150, circ 50 sks cmt down 7" up 8 1/2" wait on cmt to set up, cut off wellhead, put on markers, fill csg & cellar w/cmt.
P & A 2-8-91

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Christine Neff for TITLE Analyst - Oil Production DATE 4-9-91

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY Lyle F. Turnackliff TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUL 08 1991